Form 3160:5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

CD-A	RTESIA

FORM OMB N Expnes

5 Lease Senal No NM-69323

abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2.				6 If Indian. Allottee or trabe Name ARTE. NA 7 If Unit or CA/Agreement, Name and/or No			
1 Type of Well			<u> </u>	NA			
Oil Well X Gas	Well Other	₹.,	1	8 Well Name and	No		
2 Name of Operator				Sedge BPL I	ederal Com	1 #1	
Yates Petroleum Corporation				9 API Weli No			
3a Address 3b Phone No (include area code)				30-015-27145			
105 S. 4th Str., Artesia, NM 88210 575-748-1471				10 Field and Pool or Exploratory Area			
4 Location of Well (Footage, Sec., T., R, M., OR Survey Description)				Wildcat: Wolfcamp			
			11 County or Pansh, State				
1980'FNL & 560'FEL of Section 18-T22S-R23E (Unit H, SENE)				Eddy County, New Mexico			
12 CHECK APPROPR	IATE BOX(ES) TO INDICA	TE NATURE O	F NOTICE, RE	EPORT', OR O	THER DATA		
TYPE OF SUBMISSION		TYPE	OF ACTION				
	Acidize	Deepen	Production	(Start/Resume)	Water Shut-	Off	
X Notice of Intent	Alter Casing	Fracture Treat	Reclamation	L	Well Integri	t v	
	Casing Repair	New Construction	X Recomplete		Other		
Subsequent Report	Change Plans	Plug and Abandon	Temporarily	Abandon	,,,		
innal Atandonment Notice	Convert to Injection	Plug Back	Water Dispe	osal	:		
Yates Petroleum Corporation planting Pool with packer at on top. Prop to under balance Tubing with the amount of treate bar. Adjust the choke as necesswell to production. At some poin 6790'-6800' (11). Stimulate as a Wolfcamp perforations combined	ans to plugback and recome 9508. Load hole with treations the following Wolfcamed water specified by performany to control the well. First in the future, POOH with needed. Consider POOH was sary to consider POOH with the future.	ated water as near perforations 6 rators. Open the ow test and evantuling, packer	ecessary. Set 5960'-6984' (2 e well up a 1/4 luate. Stimula and guns. Pe d putting well l	ta CIBP at 95 5). Set packe I' choke and cate as needed erforate addition back on produ	04' with 35' or at +/-6727' drop the deto . Consider tonal Wolfcan action with all	cement F Fill mator urning np	
14 Thereby certify that the foregoing is true a	nd correct						
Name <i>(Printed∏yped)</i> Tina Hue	erta j	Title Regu	latory Complia	ance Supervis	or		
Signature (Jin)	ste,	Date Febru	uary 26, 201 ⁄	PPROVI	-p1		
	1 THIS SHACE FOR FED	ERAL OR STATE	OFFICE USE				
Approved by	Mls.	Title		MAR 1 5 20	10-1-1		
Conditions of approval, if any be attached certify that the applicant holds legal or equite which would entitle the applicant to conduct or	able title to those rights in the subject		s/i	Dustin Wir	ikle	-	

(Instructions on page 2)

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfull BUREAU OF LAND MANAGEMENT the United States any false, ficultious or fraudulent statements or representations as to any matter within its jurisdiction.

CARLSBAD FIELD OFFICE

Yates Petroleum Corporation NM-69323 – Sedge Unit #1 API: 30-015-27145 Eddy County, New Mexico

RE: Plug back/Recompletion - Conditions of Approval

There is to be no surface disturbance beyond the existing pad without prior approval. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

Contact the appropriate BLM office at least 24 hours prior to starting work. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3M BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

Submit subsequent report and new completion report once work is completed.

DHW 031210