	a marks of	. ^
Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I Energy	, Minerals and Natural Resources	June 19, 2008
1625 N French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL G	CONSERVATION DIVISION	3000560822
District III	220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	o. State on the data Brease 110.
87505 SUNDRY NOTICES AND R	EDORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL		7. Lease Name of Ont Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR P		Skip
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	BECEIVED	8. Well Number 1
2. Name of Operator	MAR 18 2010	9. OGRID Number
M.E.W. Enterprise	MAR I 6 2010	160190
3. Address of Operator	NMOCD ARTESIA	10. Pool name or Wildcat
PO Box 39, Rosswell, NM 88202	NIVIOOD 7	Elkins San Andres
4. Well Location		
Unit Letter P: 660 fe	eet from theEast line and	
Section 26	Township 7S Range 28E	NMPM County Chaves
11. Elevati	on (Show whether DR, RKB, RT, GR, etc	:.)
	4076 Oh	
12. Check Appropriate	Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENTION	TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE	===	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE	== [
DOWNHOLE COMMINGLE	_	
OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
		Attach wellbore diagram of proposed completion
or recompletion.	TEL 1103. 1 of Multiple Completions. 1	tuden wendore diagram or proposed completion
r		
1. Move in rig up and install BOP		
2. Pick up tubing and spot 70 sx class C at 2524'. WOC and tag at 2334'		
 Circulate hole with brine and mud. POH to 1956' and spot 35 sx class C. WOC and tag at 1829' 		
 4. POH to 1956' and spot 35 sx class C. WOC and tag at 1829' 5. POH to 468' and spot 35 sx class C. WOC and tag at 348' 		
6. POH to 60' and circulate cement to surface. Pumped approx. 17 sx class C		
7. Install dryhole marker and cut off anchors		
I hereby certify that the information above is true	and complete to the best of my knowled	ge and belief.
A Maria	1	0 15 10
SIGNATURE Sund Whitel	TITLE fres	DATE 3-15-10
Type or print name Russell Witel	E mail addrass: a	DHONE: -DE-1 SD SAN
For State Use Only	E-man address: Menente	9mail. Com PHONE: 575-657-2665
/////		/ /
APPROVED BY:	III LL OPPROVED FOR PROSEING OF THE	li borning DATE 07 107
Conditions of Approval (if any):	Liability under bond is retain	and ponding a constant
	of C-103 (Subsequent Report which may be found at OCD	t of Wall Discussion at 1
	Forms, www.cmnrd.state.nm.	wer rage under