

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-33170
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Butterfinger Fee Com
8. Well Number 2
9. OGRID Number 14049
10. Pool name or Wildcat Carlsbad; Strawn (Gas)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3095' GR

RECEIVED

APR 27 2010

NMOCD ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Marbob Energy Corporation	
3. Address of Operator PO Box 227, Artesia, NM 88211-0227	
4. Well Location Unit Letter <u>I</u> : <u>1980</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>10</u> Township <u>22S</u> Range <u>27E</u> NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3095' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Recompletion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Recompleted in the Strawn zone as follows:

3/5/10 - MIRU. POOH w/ tbg.

3/8/10 - Set CIBP @ 10925'. Zone abandoned: Atoka. Test plug & csg to 3000# - OK. Perf the Strawn @ 10346' - 10668' (47 shots).

3/9/10 - Set pkr @ 10247'. RIH w/ 317 jts 2 3/8" L80 tbg. Set @ 10258'. Acdz Strawn perfs w/ 4800 gal NE Fe 15% HCl acid.

3/11/10 - Return well to production.

3/12/10 - RDMO.

Producing Interval: Strawn @ 10346' - 10668'.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Briggs TITLE Production Manager DATE 4/26/10

Type or print name Diana J. Briggs E-mail address: dbriggs@marbob.com PHONE: (575) 748-3303

For State Use Only

APPROVED BY: David Gray TITLE FS DATE 4-28-2010

Conditions of Approval (if any):