Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB NO 1004-0137 Expires March 31, 2007

5 Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

5 Lease Serial No
NM-05608
6 If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.					
SUBMIT IN TRIPLICATE - Other instructions on reverse side 1 Type of Well				7 If Unit or CA/Agreement, Name and/or No North Indian Basin Unit	
				8 Well Name and No	
2 Name of Operator				North Indian Basin Unit	#21
	attn: Jereme Robinson			9. API Well No.	
3a Address	i	Phone No (<i>include ai</i>		30-015-28621	
P.O. Box 4294, Houston, TX 77210 4 Location of Well (Faorage, Sec., T. R. M., or Survey		(713) 366-31	60	10 Field and Pool, o Indian Basin M	
UL "F" 2245' FNL & 1815' FWL	те (стрион)			Thuran basin in	orrow-das
Sec. 11, T-21-S, R-23-E				11 County or Parish	, State
				Eddy County	NM
12. CHECK APPROPRIATE	BOX(ES) TO INDICAT	E NATURE OF	NOTICE, REPO	ORT, OR OTHER	DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen			Water Shut-Off
Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamatio Recomplete	7	Well Integrity Other
Final Abandonment Notice	Change Plans	Plug and Abandon	X Temporaril	y Abandon	
	Convert to Injection	Plug Back	Water Disp	osal	
following completion of the involved operations testing has been completed. Final Abandonment determined that the final site is ready for final insp. TD: 9482 PBTD: 9463 Perfs: 9314- OXY USA WTP LP request the well. This well is in a pilot project. OXY to evaluate the zone, recomp. This well. If recompletion unsu. OXY personnel will meet with BLM office in Carlsbad. OXY will T/NMOCD. SUBJECT TO LIKE APPROVAL BY STATION APPROVAL BY STATION STATIAN STATION STATION S	Notices shall be filed only afterection) 9420 be T/A for a period of to recomplete 40+ we lete a determined number of the cessful OXY will P&W and NMOCD staff in the A and MIT test the well as SEE COM	of 4 years with the state of th	n an annual rzone. The over the country of the recome t	re-up of the The time requested rse of 4 years 5/26/2010 at the mendation of the Acces	d, and the operator has (A status. I will allow to include he BLM
14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)		Title			
Jereme Robinson		Regu1	atory Analys	st	
Chetti i		Date 05/11/	2010		
ТНІ	S SPACE FOR FEDERA	L OR STATE OF	ICE USE		
Approved by /s/ JD Whitlock	le le	Title 1/5	7	Date 6	17/12
Conditions of approval, if any, are attached. Approval certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations.	of this notice does not warrant to those rights in the subject lea	or Office	,		1/10

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leakoff will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

NIBU #21. Well may be approved to be TA/SI for a period of 1 Year ending 6/7/2011 after a MIT is ran and a subsequent report is submitted. This will be the last and only TA/SI approval until an approved plan of operations is submitted and approved for wells in Indian Basin. Well must be P&A or plans to return to beneficial use submitted by June 7, 2011.