Form 3160-5 (April2004)

UNITEDSTATES DEPARTMENT OF THE INTERIOROCD-ARTESIA BUREAU OF LAND MANAGEMENT

FORMAPPROVED OM B No 1004-0137 Expires: March 31, 2007 5. Lease Serial No.

Water Shut-Off

Well Integrity

Ī	Ni

SUNDRY	NOTICES	AND	REPORTS	ÓΝ	WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.

NM24160	B [*]	V 1000	
6. If Indian, Allotte	or Tribe Name_9	2010	
j			

SUBMIT IN TRIPLICATE - Other instructions on re	
1. Type of Well Gas Well X Other	NM88491X 8. Well Name and No.
2. NameofOperator St. Mary Land & Exploration Co. 3a. Address 3b. PhoneNo. (a) 3300 N. A Street, Bldg. 7, Ste. 200 Midland, TX 797(432)68	
4. Location of Well (Footage, Sec , T., R., M., or Survey Description) Sec. 35 - T-19S-R29E 1350 FSL & 2520 FEL	Parkway; Delaware 11. County or Parish, State Eddy Co. New Mexico
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NA	ATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPEOF ACTION

TYPE OF ACTION

Reclamation

Production (Start/Resume)

X Otheradd Perfs New Construction Recomplete __ Subsequent Report _ Change Plans ☐ Temporarily Abandon Plug and Abandon Final Abandonment Notice ☐ Convert to Injection JPlugBack 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once

testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

Application has been made with the NMOCD to increase injection intervals to include 3918 - 4406'. Upon approval from NMOCD. PDU 508 - Proposed Recompletion Procedure

Deepen

☐FractureTreat

- 1. Acidize exising perfs down tubing
- 2. Set RBP

Notice of Intent

3. Shoot proposed perfs @ 3943' - 4313'.

determined that the site is ready for final inspection.)

X Acidize

AlterCasing

- 4. Frac proposed perfs down tubing
- 5. Remove RBP
- 6. Return well to water injection

SEE ATTACHED FOR CONDITIONS OF APPROVAL

SUBJECT TO LIKE APPROVAL BY STATE

DISTALL						
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)						
Donna Huddleston	Title	Production Tech				
Signature Dopper Suddlyfor	Date	05/24/2010		ΔPPF	SUNED	
THIS SPACE FOR FEDERAL	OR:	STATE OFFICE U	SE		TOVED	7
Approved by		Title		DateUN	7 2010	
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.	1	Office	Bt	/s/ Chr	ris Walls ID MANAGEME	NT
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any m	person atter v	knowingly and willfully to vithin its jurisdiction.				Inited


(Instructions on page 2)

WELLBORE DIAGRAM PARKWAY DELAWARE UNIT #508

LEASE: PDU WELL NO. 508 API #: 30-015-30029

LOCATION: 1350' FSL & 2520' FEL UL: J SEC: 35 T: 19S R: 29E SPUD: 1/01/98 FIELD: PARKWAY GL: 3328' CT/ST: EDDY,NM COMP: 1/98


STATUS: WATER INJ. KB: DF: INITIAL FORM:DELAWARE "C"



PBTD: 4360' FC TD: 4400'

EWS

PROPOSED WELLBORE DIAGRAM PARKWAY DELAWARE UNIT #508



PBTD: 4360' FC TD: 4400'

Parkway Delaware Unit 508 30-015-30029 St. Mary Land and Exploration June 7, 2010 Conditions of Approval

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location as H2S has been reported from wells in the area.
- 4. Submit subsequent sundry with injection rate, pressure and current well bore schematic.

CRW 060710