## Form 3160-5 (February 2005)

## N.M. Oil Gons. DIV-Dist. 2

UNITED STATES 1301 W. Grand Avenue

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT BUREAU DE LAND MA

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND	REPORTS ON WELLS
at usa this form for prope	soolo to drill ay to yo antay a

SUBMIT IN TRIPLICATE - Other instructions on page 2.

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

3. Lease Serial No. NMNM-2824	The state of the s	
6. If Indian, Allottee	THE EIVED	7
	JUL 8 2010	L
 7. If Unit of CA/Agr	eement, Name and/or No.	Γ

1. Type of Well			LIVINOCD ARTESIA	
✓ Oil Well Gas Well Other			8. Well Name and No. Stevens Federal No. 1	
2. Name of Operator Thornton	Operating Corporation	,	9. API Well No. 30-005-62834	
3a. Address PO Box 335; Fort Worth,	25	8b. Phone No. (include area co (817) 361-1909	ode) 10. Field and Pool or Exploratory Area Lone Wolf Devonian, South	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Parish, State	
2190 FNL, 990 FEL, Sec. 28, T 13 S , R.29 E, NMPM			Chaves County, New Mexico	
12.	CHECK THE APPROPRIATE BOX	K(ES) TO INDICATE NATUR	RE OF NOTICE, REPORT OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity	
Colors to	Casing Repair	New Construction	Recomplete Other	
✓ Subsequent Report	Change Plans	✓ Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
the proposal is to deepen du	ectionally or recomplete horizontally	, give subsurface locations an	ed starting date of any proposed work and approximate duration thereof. If d measured and true vertical depths of all pertinent markers and zones. BLM/BIA. Required subsequent reports must be filed within 30 days	

10/7/08 - MIRU, ND Wellhead; NU BOP; SDFN

determined that the site is ready for final inspection.)

10/8/08 - RIH with Gauge Ring to 4630'; POH; RIH picking up work string; wash down and tag @ 4870; notify BLM; SDFN

10/9/08 - Wash down to 5100'; Rec'd permission from BLM to perf and plug well; RIH and perf @ 5100; RIH with packer; could not pump into perfs; spot 50 sacks@ 5100'; POH; SDFN

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

10/10/08 - RIH and tag @ 4753; Circulate plugging mud; POH; RIH and perf @ 2150'; RIH with packer; held at 1000#; spot 25 sacks; POH; WOC; RIH and tag @2150'; POH; RIH and perf @ 360'; SDFN

10/11/08 - Circ 110 sxs to surface in and out of casing; RD; Dig out wellhead; cut off wellhead; cut off anchors; level location; clean up location;

10/13/08 - Checked well to insure there was no flow; well was good; Move out

APPROVED FOR 6 MONTH PERIOD ENDING APR 1 3 2009

APPROVED AS TO PLUGGING OF THIS
WELL BORE. LIABILITY UNDER BOND
IS RETAINED UNTIL SURFACE RESTORATION
IS COMPLETED

	IS COMPLETED	
14 I hereby certify that the foregoing is true and correct.  Name (Printed/Typed)  Robert L Thornton	Title president	
Signature Pled Hond	Date 10/08/2010 04/08/10	
THIS SPACE FOR FEDE	RAL OR STATE OFFICE USE	,
/S/ DAVID R. GLASS	PETROLEUM ENGINEER	Date MAY 1 1 2010
Conditions of approval, if any, are attached. Approval of this notice does not warrant or or that the applicant holds legal or equitable title to those rights in the subject lease which wo entitle the applicant to conduct operations thereon.		FICE
		0.1 11 . 10

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.