

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

WELLS REGISTRATION FORM
WELLS REGISTRATION FORM
WELLS REGISTRATION FORM

WELLS REGISTRATION FORM
WELLS REGISTRATION FORM
WELLS REGISTRATION FORM

SUNDRY NOTICES AND REPORTS ON WELLS REGISTRATION DIVISION

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. NAME OF OPERATOR Enron Oil & Gas Company		3. ADDRESS OF OPERATOR P. O. Box 2267, Midland, Texas 79702		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 1980' FWL		5. ELEVATIONS (Show whether SP, ST, OR, etc.) 3642.5' GR		6. IF INDIC. ALLOWED ON THIS NAME NM 261		7. UNIT AGREEMENT NAME		8. FARM OR LEASE NAME Canadian Kenwood Federal		9. WELL NO. 1		10. FIELD AND POOL, OR WILDCAT Shugart, North Bone Spring		11. SEC. T. R. M. OR BLM AND SURVEY OF AREA Sec. 17, T18S, R31E		12. COUNTY OR PARISH Eddy		13. STATE NM	
--	--	--	--	--	--	--	--	---	--	---	--	------------------------	--	---	--	------------------	--	--	--	---	--	------------------------------	--	-----------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data											
NOTICE OF INTENTION TO:						SUBSEQUENT REPORT OF:					
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL		FRACTURE TREAT		ALTERING CASING	
BROOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*		REPAIR WELL		CHANGE PLANS	
10ther. Recomplete from Morrow		X		(Other)		(Note: Report results of multiple completion s. Well Completion or Recompletion Report and Log form.)					

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Application to recomplete from Morrow to Bone Spring formation.

Trip out of hole with tubing & packer.

Set CIBP at 11,500' & dump 35' of cement on top.

Perforate Bone Springs carbonate from 8956' to 8980' with 2 shots/ft & acidize with 3000 gal of 15% HCL-FE acid.

Flow and/or swab test.

Perforate Bone Springs carbonate from 8858' to 8874' with 2 shots/ft.

Trip in hole with RBP & retrievable packer. Set RBP at 8930'+/-.

Acidize perms 8858' to 8874' with 2000 gal of 15% HCL-FE acid.

Flow and/or swab test. Release packer & TIH to retrieve RBP.

Trip in hole with 2-3/8" tubing.

Swab and flow to producing facilities.

18. I hereby certify that the foregoing is true and correct					
SIGNED <u>Betty Glendon</u>		TITLE <u>Regulatory Analyst</u>		DATE <u>11/30/89</u>	
(This space for Federal or State office use)					
APPROVED BY <u>ONE BLM</u>		TITLE <u>Principal</u>		DATE <u>12-5-89</u>	
CONDITIONS OF APPROVAL, IF ANY:					

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.