State of New Mexico Form C-103 Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District 1 WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-015-10177 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III FEE 🗀 STATE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 B-9646 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A MONTEREY STATE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number CIMAREX ENERGY CO. OF COLORADO ZENO FARRIS ATTN: 3. Address of Operator 10. Pool name or Wildcat 600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701 SHUGART (YATES, 7-RIVERS, QN., GB) 4. Well Location 1650 Unit Letter feet from the SOUTH 2310 line and feet from the line Township 18S Range EDDY County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 15 3,571' - GR Pit or Below-grade Tank Application or Closure 🔀 Pit type STEEL Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \* Distance from nearest surface water Below-Grade Tank: Volume\_\_\_\_bbls; Construction Material \* NONE WITHIN 1,000' Pit Liner Thickness: \_ 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ... REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND X **ABANDONMENT** CASING TEST AND **MULTIPLE** PULL OR ALTER CASING COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date

10/27-28/10: POOH W/ RODS X TUBING.

10/29/10: SET 5-1/2" CIBP @ 2,550'; PUMP A 25 SX. OMT. PLUG @ 2,550'-2,350'; CIRC. WELL W/ PXA MUD; PERF. X SQZ. A 45 SX. CMT. PLUG @ 2,096'; WOC X TAG TOP OF CMT. PLUG @ 1,947'.

of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of broposed Work 100 and 200 and 200

10/30/10: PERF. X SQZ. A 65 SX. CMT. PLUG @ 950'; WOC X TAG TOP OF CMT. PLUG @ 703'; PERF. X CIRCULATE TO SURFACE A 75 SX. CMT. PLUG @ 150'-3'; DIG OUT X OUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE CASINGS X INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan AGENT

SIGNATURE.

TITLE - :

11/01/10 DATE \_\_

NMOCD ARTESIA

E-mail address:

DEYLER@MILAGRO-RES.COM

Telephone No. 432.687.3033

Type or print name DAVID A. EYLER

For State Use Only APPROVED BY

Conditions of proval, if any:

or recompletion.

Approved for plugging of well hore only. Hability under bond is retained pending receipt THE 103 (Subsequent Report of Well Plugging)

which may be found at OCD Web Page under Forms, www.emnrd.state.nmrus/ocd.

DATE 11/4/200