District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

2RP. 482

## **Release Notification and Corrective Action**

nMB16	03215	8479			OPERATOR				Initial Repo	rt X Fin	al Report	
Name of Company: Judah Oil, LLC						Contact: Blaise Campanella						
Address: PO Box 568, Artesia, NM 88211-0568						Telephone No.: 575-748-5488 NMOCD 2RP No.: 482						
Facility Nar	ne: Oxy	Γ-Bone Feder	SWD	I	Facility Type: SWD API No.: 30-015-32122							
Surface Ow	ner: Fede	ral	Mineral C	wner: F	r: Federal Lease No.: SWD-950							
				LOCA	TION	OF REI	LEASE					
Unit Letter C	Section 33	Township 18S	Range 31E	Feet from the 660		South Line FNL	Feet from the 1980	East/West Line FWL		County Eddy		
				Longitud	e							
NATURE OF RELEASE												
Type of Rele	ase: Unaut	horized Produ							Recovered: None			
Source of Release: Tanker truck which obtained the produced water										l Hour of Discovery:		
from an unknown foreign source.										er 2010 App	orox.1300	Нгѕ.
Was Immediate Notice Given?  X Yes ☐ No ☐ Not Required						If YES, To Whom? Mike Bratcher						
By Whom? Cheryl Winkler						Date and Hour: Message @ Approximately 1330.Hrs						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse RECEIVED						
☐ Yes X No							' N/A		' '			
If a Watercourse was Impacted, Describe Fully.*						OCT <b>26</b> 2010						
N/A						NMOCD ARTESIA						
Describe Cause of Problem and Remedial Action Taken.* At an unknown date and time, a tanker truck hauling produced water from a foreign source illegally discharged its contents on both the pad area of the SWD and along the access road which eventually flowed off the roadbed into the adjacent ditch. No vacuum trucks were called because by the time the spill was discovered horizontal and vertical absorption had maximized, leaving no standing produced water on the surface. After notification to the NMOCD, plans were made to excavate the contaminated material and haul it to disposal.  Describe Area Affected and Cleanup Action Taken.* Due to the fact this discharge event was discovered after soil absorption had occurred, excavation was the only realistic option. Sampling determined the level of soil chlorides exceeded regulatory limits. Once excavation had occurred this area was again												
sampled to verify compliance. Please refer to the Corrective Action Plan and Final Remediation Report for details.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature:						OIL CONSERVATION DIVISION						
Printed Nar	ne: Blais	e Campanel		A	Approved by Distrigate and provided 11/4 Dranden							
Title: Mem		<u> </u>		A	Approval Date: Expiration Date:							
E-mail Add	ress: jud	ahoil@yaho	o.com		c	onditions of	Approval: NA	()		Attached		
Date: 25 O	ctober 20	10 1	Phono: 5	75 749 5499		Chaint -						