Form 3160-5 (August 2007)

UNITED STATES OPERATOR'S COPY DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires July 31, 2010

Do not use this form for proposals to drill or to re-enter an	5. Lease Serial No. NM-0557142
abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name NA
SUBMIT IN TRIPLICATE - Other instructions on page 2.	7. If Unit or CA/Agreement, Name and/or No.
.d. Type of Well	NMNM-111025X
	8. Well Name and No.
the state of the s	NDDUP Unit #77
	3. API Well No. 30-015-26949
	10. Field and Pool or Exploratory Area
	Dagger Draw; Upper Penn, North
	11. County or Parish, State
	Eddy County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REI	PORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Acidize Deepen Production (St	art/Resume) Water Shut-Off
Notice of Intent Alter Casing Fracture Treat Reclamation	Well Integrity
Casing Repair New Construction Recomplete	Other
Subsequent Report Change Plans X Plug and Abandon Temporarily A	
	0
Final Abandonment Notice Convert to Injection Plug Back Water Disposa	11.11.03
testing has been completed. Final Abandonment Notices must be filled only after all requirements, including reclamation, have been completed determined that the site is ready for final inspection. 10/14/10 Loaded casing. Tested to 500 psi, good. NU BOP. Set a 7" 10K Alpha CIBP as of cement on top of CIBP to give 35'. 10/15/10 Tagged cement on top of CIBP at 7655'. Loaded hole with mud gel. Pumped 2 "C" cement at 5681'. Est TOC at 5313'. 10/18/10 Tagged cement plug at 5403'. Pumped 25 sx Class "C" cement at 3451'. Est TOC at 5310'.	t 7702'. Capped with 3 runs 75 bbls. Pumped 60 sx Class
tag. Pumped 25 sx Class "C" cement at 2210'. Est TOC at 2056'. Did not have "C" cement at 1177'. WOC 2 hrs. Tagged cement plug at 990'. Pumped 25 sx 149' up to surface. ND BOP. Topped well off with cement. 10/26/10 Dug out cellar and cut off wellhead. Had to put 20 sx cement down 8-5/8" casir Filled cellar back in and dug up anchors. Cleaned location. WELL IS PLUGGE	e to tag. Pumped 40 sx Class Class "C" cement plug from g. Installed dry hole marker D AND ABANDONED.
"C" cement at 1177'. WOC 2 hrs. Tagged cement plug at 990'. Pumped 25 sx 149' up to surface. ND BOP. Topped well off with cement. 10/26/10 Dug out cellar and cut off wellhead. Had to put 20 sx cement down 8-5/8" casir Filled cellar back in and dug up anchors. Cleaned location. WELL IS PLUGGE Accepted Liability Surface 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	e to tag. Pumped 40 sx Class Class "C" cement plug from g. Installed dry hole marker. D AND ABANDONED. ed as to plugging of the well bore, y under bond is retained until restoration is completed.
"C" cement at 1177'. WOC 2 hrs. Tagged cement plug at 990'. Pumped 25 sx 149' up to surface. ND BOP. Topped well off with cement. 10/26/10 Dug out cellar and cut off wellhead. Had to put 20 sx cement down 8-5/8" casir Filled cellar back in and dug up anchors. Cleaned location. WELL IS PLUGGE Accepted Liability Surface Reclamation Due 4/16/21/ 14. Thereby certify that the foregoing is true and correct	e to tag. Pumped 40 sx Class Class "C" cement plug from g. Installed dry hole marker. D AND ABANDONED. ed as to plugging of the well bore, y under bond is retained until restoration is completed.
"C" cement at 1177'. WOC 2 hrs. Tagged cement plug at 990'. Pumped 25 sx 149' up to surface. ND BOP. Topped well off with cement. 10/26/10 Dug out cellar and cut off wellhead. Had to put 20 sx cement down 8-5/8" casir Filled cellar back in and dug up anchors. Cleaned location. WELL IS PLUGGE Accepted Liability Surface 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	e to tag. Pumped 40 sx Class Class "C" cement plug from g. Installed dry hole marker. D AND ABANDONED. ed as to plugging of the well bore, y under bond is retained until restoration is completed.
"C" cement at 1177'. WOC 2 hrs. Tagged cement plug at 990'. Pumped 25 sx 149' up to surface. ND BOP. Topped well off with cement. 10/26/10 Dug out cellar and cut off wellhead. Had to put 20 sx cement down 8-5/8" casin Filled cellar back in and dug up anchors. Cleaned location. WELL IS PLUGGE Accepte Liability Surface 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Tina Huerta Title Regulatory Compliance	e to tag. Pumped 40 sx Class Class "C" cement plug from g. Installed dry hole marker. D AND ABANDONED. ed as to plugging of the well bore, y under bond is retained until restoration is completed.
"C" cement at 1177'. WOC 2 hrs. Tagged cement plug at 990'. Pumped 25 sx 149' up to surface. ND BOP. Topped well off with cement. 10/26/10 Dug out cellar and cut off wellhead. Had to put 20 sx cement down 8-5/8" casin Filled cellar back in and dug up anchors. Cleaned location. WELL IS PLUGGE Accepte Liability Surface 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Tina Huerta Title Regulatory Compliance Signature Date October 27, 2010	e to tag. Pumped 40 sx Class Class "C" cement plug from g. Installed dry hole marker. D AND ABANDONED. ed as to plugging of the well bore, y under bond is retained until restoration is completed.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction