

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NHmw 1035731740

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 105 South 4th Street, Artesia, NM 88210	Telephone No. 575-748-1471	
Facility Name Serrano Federal #1	API Number 30-015-28166	Facility Type Battery
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-92748

LOCATION OF RELEASE

Unit Letter M	Section 11	Township 19S	Range 25E	Feet from the 660	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.67000 Longitude 104.46139

NATURE OF RELEASE

Type of Release Crude Oil/Produced Water Mix	Volume of Release 50 B/O & PW Mix	Volume Recovered 39 B/O & PW Mix
Source of Release Knockout	Date and Hour of Occurrence 6/2/2010 AM	Date and Hour of Discovery 6/2/2010 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD, District II	
By Whom? Amanda Trujillo/Yates Petroleum Corporation	Date and Hour 6/9/2010 - PM (Voicemail & E-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Hole in water side nipple of knockout. Vacuum truck and roustabout crew called.		
Describe Area Affected and Cleanup Action Taken.* Area approximately 130' X 10' all contained inside berm, knockout was isolated and repaired, vacuum truck picked up remaining oil and produced water. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). Analytical results will determine next actions, same area was being addressed for release that occurred on 11/20/2008, work plan was submitted (1/23/2009), will either address release (6/2/2010) area under that work plan or submit new work plan. Depth to Ground Water: 50-99' (80' per N.M. Office of the State Engineer), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor 	
Title: Environmental Regulatory Agent	Approval Date: 3/3/2011	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: Remediation per NMOCD Rules & Guidelines	Attached <input type="checkbox"/>
Date: Wednesday, June 16, 2010	Phone: 575-748-4217	

* Attach Additional Sheets If Necessary

2RP-529