Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		October 13, 2009 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II	OH COMOTRAL MION BURGON		30-015-24129	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE	
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOS			Craft	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FC	OR SUCH	,	
·	Gas Well 🛛 Other		8. Well Number	
2. Name of Operator			9. OGRID Number	
Devon Energy Production Company	, I.P		6137	
3. Address of Operator	, 131		10. Pool name or Wildcat	
20 North Broadway, Oklahoma City, OK 73102			Pierce Crossing Northwest (Gas)	
4. Well Location				
	om the North line and 660 feet fro	om the West line		
Section 13	Township 24S Rang		Eddy County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
2994 KB; 2972' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN		
DOWNHOLE COMMINGLE	_			
OTHER:		OTHER:		
13. Describe proposed or comp	eted operations. (Clearly state all	pertinent details, an	d give pertinent dates, including estimated dat	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or reco	proposed completion or recompletion.			
D 170				
Proposed Temporary Abandonment				
1. MIRU. TOOH w/2-7/8" production tubing and packer from 11,092'.				
2. Set CIBP at +/- 11,110'. Cap w/35' cement. (Note: Open Upper Penn Shale perfs from 11156-11405. Stuck packer at 11142)				
3. Set CIBP at +/- 10,800. Cap w/35' cement. (Note: Open Wolfcamp perfs from 10828'-10975')				
4. TIH w/2-7/8" production tubing to +/- 10,000'.				
5. Notify OCD of intent to run MIT 24 hrs in advance. Circulate wellbore with lease water.				
<ul><li>6. Pressure up and run MIT for 30 minutes and chart. Submit pressure chart and sundry to OCD.</li><li>7. Request TA for one year.</li></ul>				
7. Request 1A for one year.	TA status may be gra	inted after a	RECEIVED	
	successful MIT test is			
Spud Date: Contact the OCD to schedule the MAR 15 2011			MAR 15 2011	
tact so it may be witnessed				
	LOST PRI	m 1/1/11	NMOCD ARTESIA	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
arayu wa a			7.77	
SIGNATURE June 1	TITLE Regu	latory Specialist	DATE3/14/11	
Type or print name _Judy A. Barnett E-mail address:Judith.Barnett@dvn.com_ PHONE: _405.228.8699				
For State Use Only				
		A	100 1	
APPROVED BY: Keethad Mas TITLE Compagned Official Date 3/16/11				
Conditions of Approval (if any):			• •	

•

