Submit 1 Copy To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources		Form C-103 October 13, 2009	
District I Energy, Wilherais and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 WELL API NO.			
District II	OIL CONSERVATION DIVISION	30-015-21146	
1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease L - 1648	No.
87505			
(DO NOT USE THIS FORM FOR PROPOSA	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LTION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit A Myrtle Myra	greement Name
	Sas Well Other	8. Well Number 2	
2. Name of Operator		9. OGRID Number	
Endurance Resouces LLC		270329	
3. Address of Operator		10. Pool name or Wildca	t
PO Box 1466 Artesia NM 88211		Wildcat Delaware	
4. Well Location			
Unit LetterJ:1830	feet from theSouth line and19	80feet from theEa	stline
Section 9	Township 21S Range 27E		County
	11. Elevation (Show whether DR, RKB, RT, GR, 3229 GR 3249 KB	etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON 🔀 REMEDIAL WORK ALTERING CASING			RING CASING 🗌
	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING			
DOWNHOLE COMMINGLE			
OTHER:	☐ OTHER:		
		and give pertinent dates inclu	ding estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Well started flowing water			
	* Include W/P/A	Occording.	
1/25/11 Set CIBP C 3540	# TUCIONE MILIN	procedure.	
Casing split 3418'-3445' (2) Well bore Diagrams -		ms -	The state of the s
2/11/11 C / CIDD (2.100)		RECE	IVED
2/11/11 Set CIPB @ 3400'	current & After Plu	1 1846	1
	show cso. shoes & dept	MAR 1	4 2011
Propose to P & A	Doche from Non John	10,	ADTECIA
Tag CIBP pump	Perfs, formation dept		AHTESIA
344 Cu Feet CMT 3400-1800'	other important fec	itures.	
Shoot squeeze holes at 1795'			
Pump 702 Cu Feet CMT from surface to circulate CMT inside and outside 7" csng			
		DENTIED	
		CINICI	
Spud Date:	Rig Release Date:		
<u> </u>			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	TITLE Geologist	DATE03/11/:	
Type or print name Dondall Harm	is Remail addrages sharrian marches acres	DUANE: 200 070	22
Type or print nameRandall HarrisE-mail address:rharrisnm@yahoo.com PHONE: 308-0722 For State Use Only			
David Draw TITLE FILLD SUPPLYISOF DATE 3-21-2011			
Conditions of Approval (if any): * See Above			