Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTESIA

EODM ABBOVED

FURINI APRUVEU		
OMB NO. 1004-0135		
EXPIRES: March 31, 200		

SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Serial No.		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals	NMNM36379; K 4562 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE	d. If Itidian, Another of Thise Hame		
OODMIT IN THE BOTTLE	7. Unit or CA Agreement Name and No.		
1a. Type of Well Oil Well Gas Well Other			
2. Name of Occurrence	8 Well Name and No.		
2. Name of Operator  DEVON ENERGY PRODUCTION COMPANY, LP	Cotton Draw Unit 136H  9. API Well No.		
3. Address and Telephone No.	30-015-38534		
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611	10. Field and Pool, or Exploratory		
4. Location of Well (Report location clearly and in accordance with Federal requirements)*	Paduca; Bone Spring		
200 FSL 1650 FWL N SEC 2 T25S R31E	11. County or Parish State		
BHL: 2600 FSL & 1642 FWL K SEC 35 T24S R31E Eddy NM			
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OS SUBMISSION TYPE OF ACTION			
Dooren Dooren	on (Start/Resume) Water Shut-Off		
Alter Casing Fracture Treat Reclama	ation Well Integrity		
Subsequent Report Casing Repair New Construction Recomp	rionion ing 1		
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temporal Convert to Injection ☐ Plug Back ☐ Water D	arily Abandon		
the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)  Devon Energy Production Company, L. P. respectfully requests to set the surface casing using an Ashton Oilfield Services rig. The rig plat is attached. This rig will be used only to set the surface casing and will leave the location once the surface casing has been run and cemented. Another rig will drill the remainder of the wellbore.  The surface casing will be run and cemented back to surface as per the approved APD. The well will be secured with a cap welded onto the surface casing. Another rig will be on location within 90 days after the Ashton rig has left the location. The BLM will be notified when the Ashton rig moves off location. The surface casing will be tested as per BLM Onshore Orders No.2 when the drilling rig moves on location.  SEE ATTACHED FOR CONDITIONS OF APPROVAL			
14. I hereby certify that the foregoing is true and correct			
Signed Name Judy A. Barnett X8699 Title Regulatory Specialist	Date 3/21/2011		
(This space for Federal or State Office use)			
Approved byTitle Conditions of approval, if any:	Date		
Fine to d.c.o. Section toot, makes it is entite for any person knowingly and williarly to make any department or agency or the ornined states any raise, hearings or nadations statements of representations to any maker within its jurisdiction.			
*See Instruction on Reverse Side			





95 FEET

## Cotton draw Unit 136H Devon Energy Production Company, L. P. 30 March 2011 Conditions of Approval

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Option Setting surface casing with Ashton Rig
  - a. Notify the BLM when removing the Ashton Oilfield Services Rig.
  - b. Notify the BLM when moving in the H&P Flex Rig. Rig to be moved in within 90 days of notification that Ashton Oilfield Services Rig has left the location. Failure to notify or have rig on location within 90 days will result in an Incident of Non-Compliance.
  - c. Once the H&P Flex Rig is on location, it shall not be removed from over the hole without prior approval unless the production casing has been run and cemented or the well has been properly plugged. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
  - d. BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as H&P Flex Rig is rigged up on well. CIT for the surface casing shall be performed and results recorded on subsequent sundry pressure to be 1200 psi.

**CRW 033011**