

Submit 3 Copies To Appropriate District Office  
**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
**District II**  
 1301 W. Grand Ave., Artesia, NM 88210  
**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
**District IV**  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-103  
 Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>		WELL API NO. 30-015-01438 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> 6. State Oil & Gas Lease No.
2. Name of Operator Beach Exploration, Inc.		7. Lease Name or Unit Agreement Name: West High Lonesome Penrose Sand Unit
3. Address of Operator 800 North Maricfeld, Ste. 200, Midland, TX 79701		8. Well No. 13
4. Well Location Unit Letter <u>J</u> : <u>1650</u> feet from the South <u>      </u> line and <u>2310</u> feet from the East <u>      </u> line Section <u>17</u> Township <u>16S</u> Range <u>29E</u> NMPM County <u>Eddy</u>		9. Pool name or Wildcat High Lonesome Queen
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Notify OCD 24 hours  
 prior to test. 748-1283

T & A well in March, 2004. Packer will have to be reset and Mechanical Integrity done.

*Must be completed 3-27-04*  
*Packer must be set within 100' of top Perf.*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE Engineering Analyst DATE February 17, 2004

Type or print name Lizbeth Lodle

Telephone No. 432-683-6226

(This space for State use)

APPROVED BY \_\_\_\_\_

TITLE Field Rep ID

DATE FEB 26 2004

Conditions of approval, if any \_\_\_\_\_