	State of New Mexico	)	Form C-103	
Office <u>District I</u>	Energy, Minerals and Natural I	Resources	June 19, 2008	
1625 N. French Dr., Hobbs, NM 88240 District II		,	NO. 30-015- <del>38059</del> 31 <b>7</b> 81	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DI	l 5 Indicate	Type of Lease	
<u>District III</u> 1000 Río Brazos Rd., Aztec, NM 87410	1220 South St. Francis	Dr. STAT		
District IV	Santa Fe, NM 87505	6. State Oil	& Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		•	1	
	CES AND REPORTS ON WELLS	7. Lease Na	me or Unit Agreement Name	
	SALS TO DRILL OR TO DEEPEN OR PLUG B CATION FOR PERMIT" (FORM C-101) FOR SU	СН		
1. Type of Well: Oil Well	Gas Well  Other	8. Well Nu	nber 1	
2. Name of Operator		9. OGRID I	9. OGRID Number 6137	
Devon Energy Productin Company	L. P.			
3. Address of Operator	NI 72102	l l	me or Wildcat	
20 N. Broadway, Oklahoma City, O	)K 73102	Willow Lak	e Southeast	
4. Well Location				
Unit Letter:660			m the _Westline	
Section 16			IPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
<u> </u>	2988'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
		•	1	
NOTICE OF IN		SUBSEQUENT		
			☐ ALTERING CASING ☐	
TEMPORARILY ABANDON		MMENCE DRILLING OPNS.		
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	SING/CEMENT JOB		
BOWNINGEE GOWININGEE				
OTHER:	□   oī	HER: Recompletion		
13. Describe proposed or comp	leted operations. (Clearly state all perti	nent details, and give pertiner	nt dates, including estimated date	
of starting any proposed wo	ork). SEE RULE 1103. For Multiple Co	ompletions: Attach wellbore	diagram of proposed completion	
or recompletion.				
3/15/11 – MIRU PU. POOH w/ tbg.	DIH & set CIDD @ 5650'			
3/16/11 – OWU. Perf Delaware intervals to test: 5335-5387': 5220-5276; 4953-5095': Total 291 holes. Acidize 53220-5387' w/ 5K gals				
3/16/11 – OWU. Perf Delaware inte	rvals to test: 5335-5387': 5220-5276; 4	953-5095': Total 291 holes.	Acidize 53220-5387' w/ 5K gals	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51	rvals to test: 5335-5387': 5220-5276; 4 82' w/ 4K gals w/ 7 ½% Pentol acid.		Acidize 53220-5387' w/ 5K gals	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319'	rvals to test: 5335-5387': 5220-5276; 4 82' w/ 4K gals w/ 7 ½% Pentol acid. . RU RIH w/ swab. PU pkr to 5192' &	set. Swab well.		
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid. RU RIH w/ swab. PU pkr to 5192' & RBP & set @ 5097'. Swab oerfs 5130	set. Swab well. -82'. Set pkr @ 4938' & swa	ab.	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319° 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & 5 RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 1	set. Swab well. -82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts tl	ab.  pgs. RD PU. Currently being	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319° 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid. RU RIH w/ swab. PU pkr to 5192' & RBP & set @ 5097'. Swab oerfs 5130	set. Swab well. -82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts tl	ab.  ogs. RD PU. Currently being e Delaware.	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319° 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & 5 RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 1	set. Swab well. -82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts tl	ab.  pgs. RD PU. Currently being	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319° 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & 5 RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 1	set. Swab well. -82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts tl	ab. bgs. RD PU. Currently being e Delaware.  RECEIVED	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319° 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & 5 RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 1	set. Swab well. -82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts tl	ab.  ogs. RD PU. Currently being e Delaware.	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 8 is being filed to plug back and conver	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts the to SWD further uphole in the	RECEIVED JUN 07 2011	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & 5 RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 1	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts the to SWD further uphole in the	ab. bgs. RD PU. Currently being e Delaware.  RECEIVED	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & p RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & less to being filed to plug back and conversabove is true and complete to the best of	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts the to SWD further uphole in the first than the first that the first than the first tha	RECEIVED  JUN 07 2011  NMOCD ARTESIA	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & p RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & less to being filed to plug back and conversabove is true and complete to the best of	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts the to SWD further uphole in the	RECEIVED  JUN 07 2011  NMOCD ARTESIA	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & 5RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 18 is being filed to plug back and conversabove is true and complete to the best of the	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts that to SWD further uphole in the	DATE 6/6/11	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10 :	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & p RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & less to being filed to plug back and conversabove is true and complete to the best of	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts that to SWD further uphole in the	RECEIVED  JUN 07 2011  NMOCD ARTESIA	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 8 is being filed to plug back and converge above is true and complete to the best of E-mail address: Judith.Barnet@c	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts the state of the swap state of th	DATE 6/6/11	
3/16/11 – OWU. Perf Delaware inte 7 ½% Pentol acid. Acidize 4953-51 3/18/11 – 3/19/11 - Set pkr @ 5319' 3/22/11 – 3/23/11 - Rlse pkr. RIH to 3/24/11 – Rlse pkr & RIH to RBP evaluated for an SWD well. A C-10 :	rvals to test: 5335-5387': 5220-5276; 482' w/ 4K gals w/ 7 ½% Pentol acid.  RU RIH w/ swab. PU pkr to 5192' & RBP & set @ 5097'. Swab oerfs 5130 LD 44 jts and POOH w/ 120 jts, pkr & 8 is being filed to plug back and converge above is true and complete to the best of E-mail address: Judith.Barnet@c	set. Swab well82'. Set pkr @ 4938' & swa RBP. RIH w/ SN & 120 jts that to SWD further uphole in the	DATE 6/6/11	

