Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	Monton (Martin Complete Comple
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-60164	<u> </u>
District III	1220 South St. Francis Dr.		5. Indicate Type o	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			
1220 S. St. Francis Dr., Santa Fe, NM	ncis Dr., Santa Fe, NM		6. State Oil & Ga	as Lease INO.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Double L Queen U	^J nit	
1. Type of Well:				
Oil Well Gas Well	☐ X Other	RECEIVED		
2. Name of Operator			8. Well No.	N. M. P. C.
Tipton Oil & Gas Acquisitions,			004	
3. Address of Operator	3260 OCD-ARTESIA		9. Pool name or Wildcat	
P.O. Box 1234, Lovington, NM	88260	CD-AHTESIA	Double L Queen; A	Assoc.
4. Well Location				
Unit Letter F	:feet from the	line and	feet from	n the line
Olit LetterE_	eet nom the	inte and	leet from	n thenne
Section	Township 14S R	ange 29E	NMPM Cha	aves, County
	10. Elevation (Show whether D.	R, RKB, RT, GR, etc	:.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	☐ PLUG AND ABANDON ☐	REMEDIAL WOR	к 🗆	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DE	ILLING OPNS.	PLUG AND
TEMIT OF AMELIABANDON	CHANGE FLANS	COMMENCE DRI	LLING OPINS.	ABANDONMENT
PULL OR ALTER CASING	☐ MULTIPLE ☐	CASING TEST AN	4D 🗌	
	COMPLETION	CEMENT JOB		
OTHER: CONVERT INJECT	TOR TO PRODUCER	OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.				
Release tbg. from permanent packer. POOH with tbg. GIH with work string and bailer. Knock packer to bottom of hole.				
POOH with work string and bailer. Run new rods, pump, and tbg. Set pumping unit and commence production.				
1 0 011 with work outing and outlot. Rull how road, pump, and tog. See pumping unit and commence production.				
I haraby gartify that the information shows is true and a suplet at the last Complete Last 1, 1, 1, C				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Della Mikely TITLE Secretary Treasurer DATE 2/27/04				
Type or print name for Clay Tipton Telephone No. 505-631-4121				
(This space for State/use)	\mathcal{O}	A -[][]	1) , 70	14.5
APPPROVED BY	TITLE	SUXO	sep ?	MAR 4 2001
Conditions of approval, if any.	MO ITTLE			_DATE - 4007
• • • •				