				. !/		
Submit 3 Copies To Appropriate District State of New Mexico				C15 Form C-103		
Office District I Energy, Minerals and Natural Resources				Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	TOVISOR WHITCH 25	, 1999
District II 811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION				30-005-60257		
District III 2040 South Dockers				5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505				STATE FEE E		
2040 South Pacheco, Santa Fe, NM 87505				6. State Oil & Gas Lease No.		
SUNDRY NOTE	CEC AND DEDONTE O	AT MITTER T	~			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or	Unit Agreement Na	ame:
1. Type of Well: Oil Well Gas Well Other				LE Ranch	0	
2. Name of Operator				I		
Fred F. Pool, III				8. Well No.		
3. Address of Operator				9. Pool name or W	ildcet	
P. O. Box 132, Roswell, NM 88202					San Andres,	E.
4. Well Location				<u> </u>		
Unit Letter N :	330 feet from the	South	line and 23	10 feet from	the West	line
Section 9	Township 1	1S R	ange 28E	NMPM Chaves	Country	
	10. Elevation (Show) 3701 GR	vhether D	R, RKB, RT, GR, etc.)	County	
11. Check A	ppropriate Box to Inc	dicate N	eture of Notice D	coort or Other D	~-	
NOTICE OF IN	TENTION TO	aroute 14	CLIDS	report of Other Da		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				SEQUENT REP	ORTOF: ALTERING CASIN	с П
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL		PLUG AND	277400-0
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN		ABANDONMENT	
OTHER: Return to Produ	COMPLETION	WAL .	CEMENT JOB			
	_	*	OTHER:			
 Describe proposed or complete of starting any proposed work). or recompilation. 	o operations. (Clearly st SEE RULE 1103. For 1	ate all per Multiple C	tinent details, and give completions: Attach	re pertinent dates, inc wellbore diagram of	cluding estimated of proposed completi	iate on
I intend to ret to the followin	curn this well	to ac	tive, produc	ing status	according	
1. Rig up well	service unit	and r	un tubing to	approx. 21	00 feet.	
2. Run pump an	d rods. Make v	well h	ead connecti	.ons.		
 Set pumping unit and begin producing. 					12 12 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
					4 3)	
				. 4.70	3	
I expect to begin this work on $11/21/2001$				NI NI	TEIVED ARTESIA	
					EIVED N	
				\# 0CD +	ARTESIA 28/	
I haraby gostife that the info					4650	
I hereby certify that the information a	bove is true and complete	te to the be	est of my knowledge	and belief.	6282128	
SIGNATURE A F	All	TITLE_	Operator		DATE 11/14/	2001
Type or print name Fred F.	Rook III					
(This space for State use)		~	1-011	Pelephon	ne No. 505-623	-400
APPPROVED BY	10 \	mm r	3000 19	7		
Conditions of approval, if any:		TITLE	***************************************	<u> </u>	ATE //-/5-c	,T