



N.M. Oil Cons. Div. District
1301 W. Grand Avenue
Albuquerque, NM 87102

C) 51"

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

URGENT MESSAGE NO. 1000-0155
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. TYPE OF WELL ☐ OIL WELL ☐ GAS WELL ☒ OTHER		2. NAME OF OPERATOR HERMAN V. WALLIS		Phone: 830 257-7532 Fax: 830 895-1718	
3. ADDRESS OF OPERATOR Post Office Box 291858, Kerrville, Texas 78029-1858		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 660' FWL		5. WELL NO. 2	
6. FIELD AND POOL, OR WILDCAT Sams Ranch Grayburg		7. UNIT ASSIGNMENT NAME N/A		8. NAME OF LEASE NAME Federal "14"	
9. SURV. T. & R. NO. OR BLM. AND SURVEY OR AREA Sec. 14, T14S, R28E		10. PERMIT NO.		11. ELEVATION (Show whether to, at, or, etc.) 3600' GR	
12. COUNTY OR PARISH Chaves		13. STATE New Mexico			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NATURE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT			
SHOOT OR ACIDIZE			
REPAIR WELL			
(Other)			
PILL OR ALTER CASING	☒	FRACTURE TREATMENTS	☐
MULTIPLE COMPLETE			
ABANDON*			
CHANGE PLANS			
(Other)			

(Note: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU - INSTALL BOP - RIH WITH WORKSTRING
2. SPOT 20 SXs @ 1818' - 1718' TAG
3. CIR. 9.5# MUD
4. PERFORATE @ 301'
5. SPOT 20 SXs @ 301' - 201'
6. SPOT 10 SXs @ 60' TO SURFACE
7. INSTALL DRY HOLE MARKER - CUT OFF WELLHEAD & ANCHORS - COVER PIT - RIG DOWN
8. REMOVE ALL PRODUCTION EQUIPMENT
9. RETURN LOCATION TO PRE-DRILL CONDITION

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Herman V. Wallis</u>	TITLE <u>OPERATOR</u>	DATE <u>020102</u>
(This space for Federal or State office use)		
APPROVED BY <u>Charles L. Jones</u>	TITLE <u>P.E.</u>	DATE <u>2/5/02</u>
CONDITIONS OF APPROVAL, IF ANY:		

Accepted for record
only FEB 7 2002

Instructions on Reverse Side
person knowingly and willfully to make to any department or agency of the
nents or representations on to any matter within its jurisdiction.