

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

AUG 15 1977

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator 3. Address of Operator 4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>south</u> LINE AND <u>1980</u> FEET FROM THE <u>east</u> LINE, SECTION <u>18</u> TOWNSHIP <u>6-S</u> RANGE <u>28-E</u> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name 9. Well No. 10. Field and Pool, or Wildcat 11. Elevation (Show whether DF, RT, GR, etc.) 12. County
H. D. Oden, Inc. P. O. Box 5544, Midland, Texas 79701 3979-R.T.	Chatten-Muncy 1 Denton Camp (Miss) Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was loaded w/9.5# brine mud. 2100' of 5½" casing was pulled from well.
The following plugs were placed in well:

1. 35 sx 6425 - 6137'
2. 50 sx 2100- - 1900'
3. 65 sx 1510 - 1400'
4. 10 x 15' - back to surface.

No stub plug required.

Dry hole marker 4" x 6' above ground level placed.

Pits, cellar and location filled, leveled and location cleaned of all debris.

Job complete 7-9-77

Recovered 2100' of 5 ½" casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

H. D. Oden TITLE President DATE July 27, 1977

APPROVED BY _____ TITLE _____ DATE _____