

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

AUG 15 1977

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Dry hole	
2. Name of Operator The Superior Oil Company	7. Unit Agreement Name
3. Address of Operator P. O. Box 71 Conroe, Texas 77301	8. Farm or Lease Name Chatten-Muncy "A"
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>east</u> LINE AND <u>1980</u> FEET FROM THE <u>north</u> LINE, SECTION <u>19</u> TOWNSHIP <u>6-S</u> RANGE <u>28-E</u> NMPM.	9. Well No. 1
10. Field and Pool, or Wildcat Denton-Camp (Miss)	
15. Elevation (Show whether DF, RT, GR, etc.) RKB 3973	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was loaded w/9.5# brine mud. 4545' of 5½" casing was pulled from well.

The following plugs were placed in well:

1. 35 sx plug @ 5570'-5270'
2. 50 sx plug @ 2550'-2400'
3. 65 sx plug @ 1500'-1350'
4. 10 sx plug @ 15' - back to surface

Dry hole marker 4" x 6" above ground level set.
Pits and cellar filled and location cleaned of all debris.

Job complete 7-20-77

Recovered 4543' 5½" casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. H. Olsen TITLE Agent DATE July 27, 1977

APPROVED BY _____ TITLE _____ DATE _____