

C151
OP

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-60289
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator HERMAN V. WALLIS		6. State Oil & Gas Lease No. SW-903
3. Address of Operator Post Office Box 291858, Kerrville, Texas 78029-1858		7. Lease Name or Unit Agreement Name: State-Com
4. Well Location Unit Letter 0 1980 feet from the East line and 660 feet from the South line Section 11 Township 14S Range 28E NMPM Chaves County		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3601 GR		9. Pool name or Wildcat Sams Ranch Grayburg

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRU - INSTALL BOP - RIH WITH WORKSTRING

2. SPOT 25 SXS @ 1831' - 1731' TAG

3. CIR. 9.5# MUB

4. PERFORATE @ 450'

5. SQUEEZE 35 SXS @ 450' - 350'

Leave 100' of cnt. inside csy 350'-450' TAG

6. SPOT 10 SXS @ 60' TO SURFACE.

Notify OCD 24 hrs. prior to any work done

7. INSTALL DRY HOLE MARKER - CUT OFF WELLHEAD & ANCHORS COVER PIT AND RETURN LOCATION TO CONDITION AS SPECIFIED PRE-DRILL CONDITIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Herman V. Wallis TITLE OPERATOR DATE 013102

Type or print name HERMAN V. WALLIS
(This space for State use)

APPROVED BY

Conditions of approval, if any:

Telephone No. 830 257-7532
FAX 830 895-1718

DATE

FEB 5 2002

