	DEPARTMENT O		SUBMIT IN TRIPLICA (Other instructions on verse side)	5. LEASE DESIGNATION AND SERIA
CLIVI		CAL SURVEY	NI WELL	NM 17213  6. IF INDIAN, ALLOTTER OR TRIBE
Open of use this	DRY NOTICES AN	ND REPORIS On to deepen or plug ba PERMIT—" for such pro	Ck to a different reservoir.	N/A
I. GAS		- 14 - 2		7. UNIT AGRESMENT NAME
WELL WELL 2. NAME OF OPERATOR	OTHER		UAD 9 9 1077	None 8. FARM OR LEASE NAME
= '	. Barker	ľ	MAR 2 9 1977	Phillips Federa
3. ADDRESS OF OPERATOR			a.c.c.	9. WELL NO.
	277, Roswell,			1
See also space 17 belo At surface ()()()	f NL & 660' f	WL	tate requirements.	Unnamed-San Andre
Sec	. 27, T12S, R2	7E, N.M.P.M	•	11. SEC., T., R., M., OR BLIK. AND SURVEY OR AREA Sec. 27, T12S, 1
14. PERMIT NO.	15. ELEVAT	IONS (Show whether DF, R	RT, GR, etc.)	12. COUNTY OF PARISH 13. STAT
		3567 Grd.		Chaves   NM
16.	Check Appropriate l	Box To Indicate Na	ture of Notice, Report, o	or Other Data
N	OTICE OF INTENTION TO:		# U 8	REQUENT REPORT OF:
TEST WATER SHUT-OF			WATER SHUT-OFF	RBITAIRING WILL
FRACTURE TREAT	MULTIPLE CON	MPI.ETE X	FRACTURE TREATMENT	ALTERING CASING
SHOGT OR ACIDIZE REPAIR WELL	ABANDON* CHANGE PLAN	•	8HOOTING OR ACIDIZING	ABANDON MENT
(Other)	CHANGE PLAN			sults of multiple completion on Well ompletion Report and Log form.)
ment to this work.).  Moll pumping d	ry. Propose t	o plug and	abandon on or	before 4/15/77 or wh
Well pumping d pulling unit i and will attem 15 sxs plug fr waters; a 15 s cemented # 312	s available. pt to pull the om 1250 to 135 x plug from 25 ft. and circu	Will attempt 7" casing 50 to sopara 50 to 350 ac lated with use 25# mud	t to pull 8 5/1 cemented @ 131; te San andres : ross base at 10 150 sxs; a 10 between plugs	8" casing cemented 6 grants feet. Plan to set from Upper Permian 0 3/4° surface casing with
Well pumping d pulling unit i and will attem 15 sxs plug fr waters; a 15 s cemented # 312	s available. pt to pull the om 1250 to 135 x plug from 25 ft. and circu	Will attempt 7" casing 50 to sopara 50 to 350 ac lated with use 25# mud	t to pull 8 5/1 cemented @ 131; te San andres : ross base at 10 150 sxs; a 10 between plugs	8" casing cemented 6 grants feet. Plan to set from Upper Permian 0 3/4° surface casing with
Well pumping deputing unit is and will attem 1.5 sxs plug from the same of the surface of the su	s available. pt to pull the om 1250 to 135 x plug from 25 ft. and circu ace. Plan to	Will attempt 7" casing 50 to separa 50 to 350 ac lated with use 25 # mud	t to pull 8 5/cemented 9 131; te San andres ross base at 10 150 sxs; a 10 between plugs  MARCOLOGIAN MENTO  MENTO  MARCOLOGIAN	8" casing cemented ( 3 feet. Plan to set from Upper Permian 0 3/4" surface casing sx surface plug with
Well pumping deputing unit is and will attem 1.5 sxs plug from the same of the surface of the su	s available. pt to pull the om 1250 to 135 x plug from 25 ft. and circu ace. Plan to	Will attempt 7" casing 50 to separa 50 to 350 ac lated with use 25 # mud	t to pull 8 5/cemented 9 131; te San andres ross base at 10 150 sxs; a 10 between plugs  MARCOLOGIAN MENTO  MENTO  MARCOLOGIAN	3" casing cemented of feet. Plan to set from Upper Permian 0 3/4" surface casing sx surface plug with MENICO U.S. CESTA. NEW MENICO