

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 12 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 5435

SUNDRY NOTICES AND REPORTS ON WELLS **O. C. C.**
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DRY WELL. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) **ARTESIA, OFFICE**

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name P
2. Name of Operator Garner-Murphy Oil Co.	8. Farm or Lease Name State 9
3. Address of Operator 3101 N. Encanto Dr., Roswell, New Mexico 88201	9. Well No. # 1
4. Location of Well UNIT LETTER P, 330 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 10-S RANGE 27-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3855.6 Ground	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Starting to test, shot 12 holes from 1446' to 1452', shot 8 holes from 1459' to 1463'. T. D. 1473'. Swabbed all water. Set bridge plug at 1440' shot from 1370' to 1376', 12 holes. Shot 1379' to 1384', 10 holes. Shot 1396' to 1404', 16 holes, swabbed several days all water. Set bridge plug at 1355' shot 1256' to 1266' and shot 1334' to 1343' with 38 holes, swabbed dry, let set one week no fluid came in hole. The bonding log shows no cement above 1150'. We propose to shoot casing at 1140' and pull. Our plugging proposal is to plug the stub with cement and plug the surface pipe shoe and the top, subject to State approval. Enclosed is copy of bonding log.

*Spot a 35 SK Plug @ 4 1/2" stub
" 35 SK Plug @ 250-350
" 10 SK Plug @ surface w/ marker*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lyle R. Garner TITLE Owner-Mgr. DATE Feb. 10, 1976

APPROVED BY W. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE FEB 13 1976

CONDITIONS OF APPROVAL, IF ANY: ** as noted above*