DEPARTMENT C	or to deepen or plug back PERMIT—" for such propo	R (Other instruct. on verse side)	TE BUILDED TOTOL No. 42-R1 BUILDED TOTOL NO. 42-R1 5. LEASE DESIGNATION AND BERIAL N NM 0559993 6. IF INDIAN, ALLOTTEE OR TRIBE NA
GEOLOG SUNDRY NOTICES A (Do not use this form for proposals to drill Use "APPLICATION FOR 1.	ICAL SURVEY ND REPORTS ON or to deepen or plug back PERMIT—" for such propo	I WELLS	NM 0559993
SUNDRY NOTICES A (Do not use this form for proposals to drill Use "APPLICATION FOR 1. OIL GAS D W	ND REPORTS ON or to deepen or plug back PERMIT—" for such propo	I WELLS	
(Do not use this form for proposals to drill Use "APPLICATION FOR 1. OIL GAS	or to deepen or plug back PERMIT—" for such propo	VYELLS	
		to a different_reservoir.	
	10	sals. MECEN	
2. NAME OF OPERATOR J. Penrod Toles and McClellan			7. UNIT AGREEMENT NAME
J. Penrod Toles and McClellan	<u>, , , , , , , , , , , , , , , , , , , </u>	JUL 2 2 197	8. FARM OR LEASE NAME
3 IDDRESS OF OPERATOR	Oil Corporation	U.S. GEDLODION	McCrea Federal
J. ADDRESS OF OTERAIOR		ARTESIA NEW	VEY 9. WELL NO.
Post Office Box 848, Roswell,	New Mexico 8820	CEIVED	
<ol> <li>LOCATION OF WELL (Report location clearly and i See also space 17 below.) At surface</li> </ol>	in accordance with any Sta	te requirements.	10. FIELD AND FOOL, OR WILDCAT
At sufface	₿ <b>л</b>	AR 9 1977	Wildcat 11. SEC., T., B., M., OB BLK. AND
660' FSL & 1980' FWL	8411	13/1	SURVEY OR ABNA
			Sec. 31-T9S-R26E
14. PERMIT NO. 15. ELEVA	ATIONS (Show whether DF BT	LOIA, OFFICE	12. COUNTY ON PARISH 13. STATE
<u> </u>	3707.48' GR		Chaves New Mex
16. Check Appropriate	Box To Indicate Natu	re of Notice, Report,	or Other Data
NOTICE OF INTENTION TO:	1	801	SEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALT	TER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE CO	0M PI.ETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OB ACIDIZE ABANDON*	.	SHOOTING OR ACIDIZING	ABANDONMENT* X
CHANGE PLA (Other)	NS	(Other) (Note: Report re	sults of multiple completion on Well ompletion Report and Log form.)
		· ·	avel. 10 sx Calseal plug off at 995'. Cement plug
set 950-1050'. Cement plug se	et 850-950'. Cer	ment plug set 25	0-350'. Cement plug set
at 35-135'. 15 sx plug at sur	face. Heavy muc	l was pumped bet	ween all plugs. Will
install marker and restore loc	ation to near as	original state	as possible.
	·		
		05	
		rot	Prit
		l ° I	BA 16
		( ° I	BA AL
		(° I (	BA 12
18. I hereby certify that the foregoing is true and $Q$		(° Ţ. (.	PHA 110/76
SIGNED al & M: COOL		(° F () rator	DATE 7/18/76
(This space for Federal or State office use)	(mar	(° J (• rator	DATE 7/18/76
SIGNED al & M: COOL		(° F () rator	
(This space for Federal or State office use)		(° J (• rator	

•