

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Artesia, NM 88210

NM Oil Conservation  
SUBMIT IN COMPLETION  
(Other instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

dsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO NM 0558973
2. NAME OF OPERATOR D. L. HANNIFIN OPERATING COMPANY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Drawer 2588, Roswell, NM 88201	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL, 1980' FWL Section 20, Township 14 South, Range 28 East, N.M.P.M.	8. FARM OR LEASE NAME Lillie Federal
	9. WELL NO. #4
	10. FIELD AND POOL, OR WILDCAT Sams Ranch
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 20-14-28
14. PERMIT NO.	12. COUNTY OR PARISH Chaves
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3550' G.R.	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANE

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The Lillie Federal #4 was plugged September 4, 1985, in the following manner:

1. Swabbed the 2 7/8" production string dry of fluid.
2. Mixed 100 sacks of Class "C" and pumped same down the 2 7/8" string. Squeezed the formation and left the string full of cement from top to bottom.
3. A 35 sack plug Class "C" was spotted behind 5 1/2" and 2 7/8" casing from 250' to 150'.
4. A regulation marker was erected and the location was cleaned and leveled and the Bureau of Land Management was notified for final inspection.

RECEIVED

AUG 25 '88

Post ID-2  
9-2-88  
P+H

O. C. D.  
ARTESIA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED D. L. Hannifin

TITLE Operator

DATE August 10, 1988

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

\*See Instructions on Reverse Side

