

N. M. O. & G. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Copy to:
Form approved
Budget Bureau No. 42 R1424.

LEASE DESIGNATION AND SERIAL NO.

NM-2024

6. INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Linda ¹⁸ Federal ~~18~~

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Wildcat or
~~North Linda~~

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T-6-S, R-26-E

12. COUNTY OR PARISH

Chaves

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back a well or to
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

OIL ☐ GAS ☐
WELL ☐ WELL ☐ OTHER

Dry

AUG 5 1977

NAME OF OPERATOR

Holly Energy, Inc. ✓

ADDRESS OF OPERATOR

P. O. Box 726, Artesia, N.M. 88210

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

O. C. C.
ARTESIA, OFFICE

330' FSL and 330' FWL of Section 18, T-18-S, R-26-E

4. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3738' GL

6.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☒

FRACTURE TREAT ☐

MULTIPLE COMPLETION ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

5½" casing is set @ 1292' and perforated from 1076-1120'. A CIBP is set @ 1050' and well is perforated from 1000-1020'.

Propose to plug and abandon well. Cut off 5½" casing @ approximately 650' and pull.

Set 100' plug @ 900-1000' with 15 sacks.
Set 100' Plug @ 600'-700' with 30 sacks.
Set 100' plug @ 247- 347' with 35 sacks.
Set 10 sack plug at surface.

RECEIVED

JUL 19 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

8. I hereby certify that the foregoing is true and correct

SIGNED

Robert Loyd

TITLE

Superintendent

DATE

July 18, 1977

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AUG 4 - 1977
X *Robert Loyd*
R. L. BLENNIN
ACTING DISTRICT ENGINEER

REMARKS

*Subject to BLM requirement
of ripping well pad and
access road not used.*

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment (such as any former or present production zone, or other zones with present or future fluid contents not sealed off by cement or otherwise), depths, top and bottom, and method of placement of cement plugs; kind or other material placed below; bar weight; above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and other well site conditioned for final inspection looking to approval of the abandonment.