

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other "Instruct")
(verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A		5. LEASE DESIGNATION AND SERIAL NO. NM 2359	
2. NAME OF OPERATOR Yates Petroleum Corporation ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 FNL & 2310 FWL, Sec. 6-T7S-R26E		8. FARM OR LEASE NAME Sorenson IB Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3682' GR		10. FIELD AND POOL, OR WILDCAT Linda San Andres	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit C, Sec. 6-7S-26E	
		12. COUNTY OR PARISH Chaves	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Production has declined below economic limit and as there is no apparent indication of workover economics, we propose to plug and abandon well as follows:

1. Rig up unit and pull sucker rods and pump.
2. Swab tubing for static fluid level as near as possible to seating nipple.
3. Pull tubing.
4. Dump Ready-Mix cement, with controlled flow to prevent bridging, until casing is full.
5. Weld marker to casing.
6. Grade and level location, cut all anchors below ground level and haul away all equipment.

Will notify BLM, Roswell, prior to beginning any of the above operations.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester

TITLE Production Supervisor

DATE 11-1-84

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 20 1984

*See Instructions on Reverse Side