Form 9-331 201 COLIS. 00	Form Approved. Budget Bureau No. 42-R1424
Dec. 1973 DEC. 1973 UNITED STATES Articles of	5. LEASE
DEPARTMENT OF THE INTERIOR	10 ⁻¹⁰ NM 3051
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME RECEIVED
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas . well well other P&A	Hewitt IM Federal MAR 2.2 1983 9. WELL NO.
2. NAME OF OPERATOR	1 <u> </u>
Yates Petroleum Corporation	10. FIELD OR WILDCAT NAME ARTESIA, OFFICE
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210	LINUA SA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	_ 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit P, Sec. 25-T6S-R25E
below.) AT SURFACE: 990 FSL & 330 FEL, Sec. 25-6S-25E AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Chaves NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	_
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 37 31 ' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple campletion of zone change on Form 9-330.)
CHANGE ZONES	- 241. 4 - 1
	U.S. GEOLOGICAL SURVEY
	U.S. GEÖLOGICAL SURVER Hoswell, New Mexico
ABANDON• 🗌 🕅	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
ABANDON• Xana Abandon	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
ABANDON• Xample ABANDON• Xampl	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
 ABANDON*	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
ABANDON• other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly station including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Plugged and abandoned well as follows: Plug #1: 1060-945' w/25 sacks Class "C" cent	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
 ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Plugged and abandoned well as follows: Plug #1: 1060-945' w/25 sacks Class "C" cen Plug #2: 400-300' w/25 sacks Class "C" cen Plug #3: Surface w/15 sacks Class "C" cen Installed dry hole marker. Surface will be 	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* ment nent nent
 ABANDON* ABANDON* ABANDON* About the content of the content	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* ment nent nent restored in accordance with
 ABANDON* ABA	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* ment nent nent restored in accordance with
 ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Plugged and abandoned well as follows: Plug #1: 1060-945' w/25 sacks Class "C" cent Plug #2: 400-300' w/25 sacks Class "C" cent Plug #3: Surface w/15 sacks Class "C" cent Installed dry hole marker. Surface will be Minerals Management Service requirements. Verbal approval for plugging approved by Mr. 10-5-82. 	ACGWELL, NEW MEXICO Inte all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* ment ment ment restored in accordance with Armando Lopez, MMS, Roswell on
 ABANDON* ABANDON* ABANDON* Abandone Abandone Abandone Abandoned well as follows: Abandoned well as fol	ACGWELL, NEW MEXICO Ite all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* Ment hent restored in accordance with Armando Lopez, MMS, Roswell on Set @Ft.
 ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Plugged and abandoned well as follows: Plug #1: 1060-945' w/25 sacks Class "C" cent Plug #2: 400-300' w/25 sacks Class "C" cent Plug #3: Surface w/15 sacks Class "C" cent Installed dry hole marker. Surface will be Minerals Management Service requirements. Verbal approval for plugging approved by Mr. 10-5-82. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct signed and correct signed and the provide the marker of the provide the provide the provide the marker of the provide the marker of the provide the marker of the provide the pro	ACGWELL, NEW MEXICO Inte all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* ment ment nent restored in accordance with Armando Lopez, MMS, Roswell on Set @ Ft. Secty 10-7-82
 ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Plugged and abandoned well as follows: Plug #1: 1060-945' w/25 sacks Class "C" cent Plug #2: 400-300' w/25 sacks Class "C" cent Plug #3: Surface w/15 sacks Class "C" cent Installed dry hole marker. Surface will be Minerals Management Service requirements. Verbal approval for plugging approved by Mr. 10-5-82. B. Thereby certify that the foregoing is true and correct 	ACGWELL, NEW MEXICO Inte all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)* ment ment nent restored in accordance with Armando Lopez, MMS, Roswell on Set @ Ft. Secty 10-7-82

*See Instructions on Reverse Side