

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

AUG 25 1978

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-24
7. Unit Agreement Name
8. Farm or Lease Name Dexter State
9. Well No. 2
10. Field and Pool, or Wildcat Calumet S.A.
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.
ARTESIA, OFFICE

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A QUANTIFIED RESERVOIR.
SEE APPLICATION FOR PERMIT FORM C-101 FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. Name of Operator
Elk Oil Company ✓

2. Address of Operator
P. O. Box 310, Roswell, New Mexico 88201

3. Location of Well
UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 36 TOWNSHIP 12S RANGE 26E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3512 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

16. Describe in brief or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandon well as follows:

Pulled 80' of 8 5/8" casing

Placed the following plugs:

35 sx plug @ 1530'

35 sx plug @ 1100-1000 (Base of 8 5/8" casing)

100' plug in and out of 8 5/8" casing stub to surface

Drilling mud between all plugs.

Place standard 4' x 4' dry hole marker at surface.

Location cleaned and leveled, ready for inspection.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE President DATE 8/24/78

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE FEB 16 1979

CONDITIONS OF APPROVAL, IF ANY: