

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-481	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Southland Royalty Company ✓		8. Farm or Lease Name Sams-State Comm.
3. Address of Operator 1100 Wall Towers West, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>north</u> LINE AND <u>660</u> FEET FROM THE <u>east</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14S</u> RANGE <u>28E</u> NMPM.		10. Field and Pool, or Wildcat Sams Ranch (Grayburg)
15. Elevation (Show whether DF, RT, GR, etc.) 3568' GR		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-27-80 Riggged up. Killed well with brine water.

2-28-80 Set CIBP @ 1605'. Dump 35' cmt. on plug. Displace hole with 9.5# mud. Spot cmt. plug from 309-209'. Spot cmt. plug from 30' to surface. Clean location and install dryhole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Harnay Carr TITLE District Engineer DATE 3-5-80

APPROVED BY M. E. Sturtevant TITLE OIL AND GAS INSPECTOR DATE MAY 28 1980

CONDITIONS OF APPROVAL, IF ANY: