

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

APR 25 1980

RECEIVED

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS O. C. D.

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Coronado Exploration Corp.	8. Farm or Lease Name Plains Radio
3. Address of Operator 1005 Marquette NW Albuquerque, NM 87102	9. Well No. #1
4. Location of Well UNIT LETTER <u>E</u> <u>1680</u> FEET FROM THE <u>north</u> LINE AND <u>800</u> FEET FROM THE <u>west</u> LINE, SECTION <u>27</u> TOWNSHIP <u>9S</u> RANGE <u>28E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat SA
15. Elevation (Show whether DF, RT, GR, etc.) 3828 Gr	12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

- 4-2-80 Pulled rods and tubing. Set first plug with 30 sx Dowell Class C cement with 2% CaCl. TD- 2526- (2525-435').
- 4-3-80 Ran a free point and shot 4-1/2" casing off at 1510'; pulled casing and set second plug with 35 sx Dowell Class C 2% CaCl cement (1430-1530). Set third plug from 650-750.
- 4-4-80 Set fourth plug with 35 sx Dowell Calss C 2% CaCl cement (350-450) WOC 2 hours. Set fifth plug and dry hole marker at surface.

Will clean pits and be ready for inspection 5-15-80

Post ID- 2  
5-2-80  
P & A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CORONADO EXPLORATION CORP.

SIGNED BY: [Signature] TITLE ENGINEER DATE APRIL 23, 1980

APPROVED BY: [Signature] OIL AND GAS INSPECTOR DATE JUL 1 1980

CONDITIONS OF APPROVAL, IF ANY: