

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SALE TAX	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 2 1979

D. C. C.

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS **ARTESIA OFFICE**

DO NOT USE THIS FORM FOR A REPORT ON A WELL OR TO OPEN OR PLUG A WELL TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO OPEN OR PLUG A WELL FOR SUCH PURPOSES.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator **PLANET, INC.**

Address of Operator **P.O. Box 31718, Amarillo, TX 79120**

Location of Well

UNIT LETTER **P** **330** FEET FROM THE **South** LINE AND **330** FEET FROM THE **East** LINE, SECTION **30** TOWNSHIP **10 S** RANGE **29E** NMPL.

13. Elevation (Show whether DF, KT, GR, etc.) **3880 G.L.**

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement No.

6. Name of Lease Name **Whittenburg "H"**

9. Well No. **1**

10. Field and Pool, or Wildcat **Wildcat-San Andres**

12. County **Chaves**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

ENFORCE REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
ULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOG ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6-11-79 T.D. 2949 feet. Plugged and abandoned with verbal permission as follows:
Pulled rods and tubing, ran 2935 feet of 2-3/8" tubing, Pumped 35 sx plug- 2949 to 2660
- 6-12-79 Tagged cement @ 2660, pumped 9 sxs of gel, cut and pulled 2159 feet of 5-1/2" casing. Ran tubing and tagged cut off at 2159 pumped 25 sxs cement, plug 2159-1959. Pulled tubing to 1775 feet, pumped 35 sxs cement, plug at 1775-1600 feet.
- 6-13-79 Tagged cement plug at 1600 feet, pulled up at set 35 sx plug at 650 - 550 feet, half in and out of surface casing. Laid down tubing and spotted sack and rope plug 28 feet down. Put 15 sx surface plug rigged down and erected dry hole marker. Mud spotted between all plugs. Will Will notify when location is ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

W. B. M. C. Agent DATE 7-2-79

B. W. Weaver Field Rep DATE 11-1-79

ADDITIONS OF APPROVAL, IF ANY: