

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form O-101
Revised 10-1-73

RECEIVED

JAN 21 1980

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
ALBUQUERQUE	1
U.S. GEOLOGICAL SURVEY	
LAND OFFICE	
OPERATOR	1

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. D.

ARTESIA OFFICE

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Coronado Exploration Corp.

3. Address of Operator
1005 Marquette NW Albuquerque, NM 87102

4. Location of Well
UNIT 11, 1/4 A 660 FEET FROM THE north LINE AND 660 FEET FROM
the east 28 10S 28E

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement No.

8. Name of Lessee
J.P. White E

9. Name of Well
LL Ranch - San Andres

15. Depth (feet) (Surface, 100, 200, 300, etc.)
1788.1

16. Check Appropriate Box To Indicate Nature of Notice Report or Order

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING Casing ☐
TEMPORARILY ABANDON ☐	CHANGE PLANT ☐	COMMENCE DRILLING OPERATIONS ☐	PULL AND RE-CEMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CEMENT JOBS AND CEMENT JOBS ☐	

17. Description of Work or Operation (Clearly state all pertinent details, including dates, including any other work done on well, any work done on well, any work done on well)

1" rods and tubing.
Run cement bond log to determine top of cement behind 4 1/2" casing.
Cut and pull 4 1/2" casing.
1st plug: 25 sacks in bottom of hole; will cover 385' (all perfs).
2nd plug: 35 sacks placed in a manner to cover both above and below 4 1/2" stubs equally. *tag*
3rd plug: 10 sacks; set dry hole marker.
Space between plugs will be filled with mud.
Proposed date of plugging will be January 23, 1980.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* Engineer DATE 1-18-80

APPROVED BY *W. A. Livessett* SUPERVISOR, DISTRICT II DATE JAN 21 1980

CONDITIONS OF APPROVAL, IF ANY:
Spata 35 sack plug 350-450 + tag
Plugging