



PETROLEUM EXPLORATION / INVESTMENT / DRILLING / PRODUCTION  
600 AMARILLO PETROLEUM BUILDING / AMARILLO, TEXAS 79101

THE HARLOW CORPORATION PHONE (806) 372-7381

RECEIVED

October 17, 1980

OCT 20 1980

O. C. D.  
ARTESIA, OFFICE

Mr. W. A. Gressett, District Supervisor  
Energy and Mineral Department  
Oil Conservation Commission  
P.O. Drawer DD  
Artesia, NM 88210

Re: O'Brien Fee "19"-2  
(2-0-19-8-29)

Dear Mr. Gressett:

We have not done anymore work since our last report to you. Drilling requirements and a shortage of manpower seems to conspire against us. The records show that the well was originally perforated over a large interval and heavily treated. Our present procedure of small zones and light treatments seems to be working better. We think it possible to make a small well at this location but other locations look to be more profitable.

We think now that we will do additional perforations from 2663-67 and treat only the zone from 2662-80 relatively lightly. We also plan to isolate and treat from 2632-34.

Form C-103 will be filed just as soon as we can get to the work,

Yours very truly,

THE HARLOW CORPORATION

W. B. LaFon  
Production Engineer

WBL/ps