

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

c/sf
dp

Form C-103
Revised March 25, 1999

WELL API NO. 30005-60578
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. ☒

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ Injection ☐	7. Lease Name or Unit Agreement Name: Twin Lakes San Andres Unit
2. Name of Operator Concho Oil & Gas Corp.	7. Well No. 12
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701	8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)
4. Well Location Unit Letter <u>P</u> : <u>330</u> Feet from the <u>South</u> line and <u>330</u> feet from the <u>East</u> line Section <u>25</u> Township <u>8S</u> Range <u>28E</u> NMPM Chaves County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3950.5 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐


SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Concho Oil & Gas Corp. respectfully requests approval to plug and abandon the TLSAU #12 well according to the following procedure:

1. Notify NMOCD Artesia 24 hrs prior to commencement of procedure.
2. Set 150' cmt plug from 2560-2740'. WOC. Tag.
3. Circ hole w/ mud. 2518' to 2730'
4. Cut csg @ 1985' & POOH.
5. Set 100' cmt plug @ 1935-2035'. WOC. Tag.
6. Set 100' cmt plug @ 1540-1640'. 1400' to 1500'
7. Set 100' cmt plug @ 860-960'.
8. Circ cmt from 177' to surface.
9. Cut off wellhead & install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Analyst DATE 9-28-01

Type or print name Terri Stathos Telephone No. 915/683-7443

(This space for State use)
APPROVED BY [Signature] TITLE Field Rep ID DATE 10-10-01


Conditions of approval, if any:

TLSAU #12

Formerly - O'Brien Fee #25

Lease No.: 24988 Dist. No. : County: Chaves Field: Twin Lakes San Andres
 Section: 25 Twsp: 8S Range: 28E Unit Ltr: P Location: 330' FSL & 330' FEL
 API No. 30-005-60578

Spud Date: 07/17/79
 TD Date: 07/25/79
 Comp Date: 08/13/79



Original Perf Details: P1: 2618-2626 & 2631-2635
 2500 gals 20% acid

Add P1: 2639-2650
 Could not break down perfs. Reperforated and still couldn't break down

Nov-81 Acdz'd w/ 6000 gals 15% nitrified acid

Feb-91 Add P2: 2686, 87.5, 92, 97, 2700 Acdz'd w/ 500 gals acid & 250 gals xylene

Nov-93 Flowing @ surface. POOH w/ PE. Ran R-4 pkr on 85 jts 2 3/8".

Operator Concho Unit
Well Twin Lakes SA Unit # 12
Unit P Section 25 Township 28 Range 28
API # 30 - 005 - 60578

- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install Dry Hole Marker

* Notify OCD 24 hrs. prior to any work done

