

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ JAN - 4 1980

2. NAME OF OPERATOR

BOYD OPERATING COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 1756, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FNL, 660 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3744 GL 3757 K.B.

5. LEASE DESIGNATION AND SERIAL NO.

NM 26069

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Blakemore Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

20-9S, R26E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

GRANITE WASH

11/5/79 Rigged up completion unit, nipped up tubing head and BOP. Unloaded and strapped
178 jts of 2 3/8" tubing.
11/6/79 Picked up 174 jts of tubing w/bit to a TD of 5663', circulated hole w/2% KCL water
and spotted 100 gallons of acetic acid. POOH. Rigged up wireline to run tie in
log but had equipment failure on wireline truck.
11/7/79 Ran tie in log and perforated well @ 5605-15' / 5620-30'. Went in hole w/tubing and
packer, setting packer @ 5480'. Swabbed well dry w/no shows.
11/8/79 SITP 0# Treated well w/2000 gallons of Mod Iol acid. Formation broke @ 2800#
pumped at a rate of 3.5 bbl/min at a pressure of 3300# w/ball action. ISDP 1900#
15 min 1550#. Swabbed well dry w/no shows.
11/12/79 SITP 30# Ran swab and recovered 4 bbls of acid water, POOH. Rigged up wireline
and set plug @ 5660' w/15' of cement on top.

18. I hereby certify that the foregoing is true and correct

SIGNED (One Sgd.) GEORGE H. STEWART

TITLE Operator

DATE 12/28/79

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE [Signature]
CONDITIONS OF [Signature] IF ANY

TITLE

DATE JAN 1 1980