STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. 07 COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE	1	1
U.S.G.S.		
LAND OFFICE	1_	1
DPERATOR	1	

IL CONSERVATION DIVISIC

Form C-103

DISTRI	BUTION			h	. о. вох	2088	IVED		Revised 10-1-78
SANTAFE		1		SANTA F	E, NEW	ме Я Б Б 7 Б) P W *** **	5a. Indicate Type	of Legra
FILE		1							_ ,
U.S.G.S.						NOV 2	6 1979	State	Fee X
LAND OFF		-				1101 ~		5. State Oil & Gas	Lease No.
DPERATOR	·	<u></u>	لـــا			and in	n (**)		
				271755 1117 2500	DICON	WCIIC CTESIA	Comparions.		VIIIIIII)
		SUN	IDRY	NOTICES AND REPORTS TO DEEPLE ON FOR PERMIT - FORM C-10	KIS UN	CH TO A DIFFERENT R	ESERVOIR.		
1 10 4 00)	USE THIS FOR	APPL	ICAT 10	IN FOR PERMIT -" IFORM C-10	I) FOR SUCH	PROPOSALS.)		7. Unit Agreement	Name
1.									
WELL X	GAB WELL	Ш		OTHER-				8. Farm or Lease	Name
2. Nume of Operat	tor							Pinkie	
Ralph	n Nix	_						<u> </u>	
Address of One	erator							9. Well No.	
P.O.	Box 61	7,	Art	tesia, New Mexi	.co 81	8210		1	
4. Location of We								10. Field and Poo	
1. Lecation of wa	В		33	30 FEET FROM THE	North	LINE AND	LO FEET FROM	Undesign	ated Sa
UNIT LETTER		<u> </u>		FEET FROM THE		LINE AND			
	,			1.0	^ ~		20_E	MILLINIA	VIIIIIIIII
THE Eas	<u>st</u>	NE, S	ECTION	н 12 томизнір	<u>8-S</u>	MANGE	NMPM.	VIIIIIII	(()))))))))
	***	~~	crr	15. Elevation (Sho				12. County	THITTI
		$^{\prime\prime\prime}$		15. Elevation (5/10	068 G	D		Chaves	
		\mathcal{U}	777.						
16.		Che	ck A	Appropriate Eox To In	dicate N	ature of Notice	e, Report or Otl	her Data	
				TENTION TO:	1	· ·	SUBSEQUENT	REPORT OF:	
	NOTIC		1114	, 2					
				PLUG AND ABI	NOON	REMEDIAL WORK		ALTER	ING CASING
PERFORM REMED	AL WORK			FE00 N		COMMENCE DRILLIN	G OPNS.	PLUG A	AND ABANDONMENT
TEMPORARILY AS	ANDON					ì	£1		
PULL OR ALTER C	ABING			CHANGE PLAN	• []		erforating	& Treatme	nt
						OTHER			
OTHER									
				perations (Clearly state all po	eninent det	ails, and give pertin	ent dates, including	estimated date of	starting any proposed
17. Describe Pro work) SEE F	oposed or Cor	nple	ed Ope	erations (Crearly state are pr					
шоли,									
11/14/70	Biggod	11	n 1476	ell service uni	it. ra	n perforat:	ing gun an	d perforat	ed 11
11/14/79	Rigged	_ u	+h	o following int	erval	s: 2606-20	608-2611-2	620-2626-2	630-2632-
	shots at the following intervals: 2606-2608-2611-2620-2626-2630-2632-2636-2640-2642-2645. Came out of hole and ran tubing on packer.						er.		
	2636-2	04	0-2	042-2045: Came		OI 11010 WIII		-	
/1 - /- 0		.	1	h 2000 gallons	of 20	% NEFE acid	d. used 20	Ball Seal	ers,
11/15/79	Treate	a	MT CI	h 2000 gallons k acid treatmer	OI 20	ocovered a	cid water	with show	of oil.
	Swabbe	a	pac.	k acid treatmen	IL. K	ecovered a	Cia waser	.,	
		_			- = 20	e stere acid	A with add	itives and	1 15
11/17/79	Treate	d	wit.	h 6000 gallons	OI ZU	& NELE GCT	u with add	TCTVCB and	. 13
	Ball S	ea	ler	s. Swab into	canks.				
•									
				•					
							•		
				·		of an knowledge an	d belief.		
18. I hereby cer	nily that the	infor	mation	n above is true and complete	to the best	or in a stomredge au			
_	1/2 -	 -	111					٦.	1 /21 /70
	Man 1		1/4	M	TITLE _C	perations	manager	DATE	1/21/79
SICHED WIN	WWI J	11	1-6						
			1	/		Witness	Diconnice	, MON	1 4 7 1979
	11/)	\mathcal{U}	100014		SUPERVISOR	DISTRICT II	DAYE	1 M (10/3