

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION RECEIVED BY
P. O. BOX 2088
SANTA FE, NEW MEXICO
DEC 05 1983

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-73

3a. Indicate Type of Lease
State ☐ For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Mesa Petroleum Co.	8. Farm or Lease Name Bestwall
3. Address of Operator P. O. Box 2009 / Amarillo, Texas 79189	9. Well No. 1
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 29 TOWNSHIP 9S RANGE 25E NMPM.	10. Field and Pool, or Wildcat South Pecos Slope Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3547.5' GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Commenced P&A on 11-28-83 as follows:

Set CIBP @ 3798' plus 35' cement.
Cut 4 1/2" csg at 1600' and set 25 sx "C" at 1650'.
Ran in hole with tubing - no cement at 1600'.
Set 100 sx "C" at 1650' to 1220' and tagged with tubing.
Set 20 sx "C" from 100' to surface.
Installed dry hole marker.
Well is P&A 11-30-83.

Post ID-2
12-9-83
P&A

XC: NMOCDA-A(0+2), CEN RCDS, ACCTG, MAT CONT, MIDLAND, ROSWELL, OPS(FILE), PARTNERS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R E Maff TITLE REGULATORY COORDINATOR DATE 12-2-83

APPROVED BY Danell Moore TITLE Geologist DATE 2/10/86

CONDITIONS OF APPROVAL, IF ANY: