USF

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Completion or Recompletion Report and Log (orm.)

		Expires.	IVI MI CII	3., ., .,	, ,
5.	Lease	Designat	ion and	Serial	No

NM-14774 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE KECEIVED 1. Type of Well Oil Well Gas Well 8. Well Name and No. APR 1 () 1992 2. Name of Operator Rutter Federal #1 O. C. D. 9. API Well No. MGF Oil Corporation 3. Address and Telephone No. 30-014774-0-003 918-491-4314 10. Field and Pool, or Exploratory Area P. O. Box 21540, Tulsa, OK 74121-1540 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sand Ranch (Morrow) 11. County or Parish, State SW SE (660' FSL & 1980' FEL) of Sec. 14-10S-29E Chaves, NM 12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Conversion to Injection Altering Casing Dispose Water (Note: Report results of multiple completion on Well

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1. Set CIBP @ 9160' w/35' cmt on top.
- 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl.
- 3. Set 25 sx cmt plug @ 8000'.
- 4. Shoot & pull  $4\frac{1}{2}$ " casing (est. 5000').
- 5. Set 40 sx cmt plug 50' in & 50' out of top of  $4\frac{1}{2}$ " casing. Tag.

W6. Set 40 sx cmt plug @ 2900'. Tag Pluy

- 7. Set 40 sx cmt plug @ 400'.
- 8. Set 25 sx cmt plug @ surface.
- 9. Weld on cap and install DH marker.

Note: Both 8 5/8" & 13 3/8" casing is cemented to surface.

Estimated starting date: 5/11/92.

14. I hereby craftly that the foregoing is true and correct  Signed Can alkerburg	Charlotte Van Valken Title Technical Coordinato	
(This space for Federal or State office use)  Approved by Conditions of approval, if any:	Title	APPROVED PETER Water HESTER  APR 9 1000
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly or representations as to any matter within its jurisdiction.	and willfully to make to any department or agency	of the United States any false, lictifious or fraudulent statements
•	See Instruction on Reverse Side	ROSWELL RESOURCE AREA