

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.C.S.	
LAND OFFICE	
OPERATION	

MINERAL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED
SEP 23 1981

Form C-103
Revised 10-1-78

O. C. D.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. GIL WELL ☐ GAS WELL ☐ OTHER ☐		5a. Indicate Type of Lease State ☐ Free ☒
2. Name of Operator UNION OIL COMPANY OF CALIFORNIA /		5. State Oil & Gas Lease No.
3. Address of Operator P. O. BOX 671 MIDLAND, TEXAS		7. Unit Agreement Name
4. Location of Well UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1,980 FEET FROM THE WEST LINE, SECTION 1 TOWNSHIP 8-S RANGE 28-E		8. Farm or Lease Name O'BRIEN
		9. Well No. 1
		10. Field and Pool, or Wpdcut UNDESIGNATED(SAN ANDRES)
15. Elevation (Show whether DF, RT, GR, etc.) 4,058.1' GL		12. County CHAVES

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2,900'

PERFS. 2,585', 2,618', 2,720' 2,748'

Casing Record: 8-5/8" OD 327' 175 sx
5-1/2" OD 2,800' 225 sx

5-18-81 MI RU PU, perf 5-1/2" OD casing @ 900' & 380'. Ran 2-3/8" OD tubing to 2,690', pull up to 2,678'.
5-19-81 Plug No. 1 - spot 35 sx Class "C" cement 2,678' - 2,392', tagged top of cement 2,392'. Plug No. 2 - ran cement retainer on 2-3/8" OD tubing & set @ 705', spot 50 sx Class "C" cement, pump w/full returns to surface. Pull out of retainer leaving 5 sx on top of retainer and 20 sx below retainer to perfs @ 900' and 25 sx outside 5-1/2" OD casing. Plug No. 3 - set cement retainer on 2-3/8" OD tubing @ 181', spot 50 sx Class "C" cement and pump w/full returns to surface. Pull out of retainer leaving 2-1/2 sx on top of retainer and 20 sx below retainer to perfs @ 380' and 27-1/2 sx outside 5-1/2" OD casing. Plug No. 4 - ran 2-3/8" OD tubing to 96', spot 15 sx Class "C" cement, circulate inside 5-1/2" OD casing to surface. Pumped 9.5# mud between plugs. Weld 1/2" steel plate on top of 8-5/8" OD casing. Install 4" x 4' dry hole marker. Well P&A 5-19-81.

Posted ID-2
P&A
10-2-81

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.R. Hughes R. Hughes TITLE District Drilling Supt. DATE 9-16-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: