

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED
FEB 24 1981
O. P. S.
ARTESIA, N.M.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Free ☐
5. State Oil & Gas Lease No.
L-4039

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR APPLICATIONS TO DRILL OR TO RE-DRILL OR TO RE-LEASE TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR TO RE-DRILL OR TO RE-LEASE TO A DIFFERENT RESERVOIR.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Martin B. Muncy

3. Address of Operator
P.O. Box 196 Artesia, New Mexico 88210

4. Location of Well
UNIT LETTER A 330 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 6S RANGE 27E NMPM.

13. Elevation (Show whether DF, RT, GR, etc.)
3940.8

7. Unit Agreement Name
8. Farm or Lease Name WFM State
9. Well No. 1
10. Field and Pool, or Wildcat wildcat
12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	
OTHER ☐	
PLUG AND ABANDON ☐	
CHANGE PLANS ☐	
	REMEDIAL WORK ☐
	COMMENCE DRILLING OPS. ☐
	CASING TEST AND CEMENT JOBS ☐
	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A permanent plug was set at 2240'. Dowell pumped 25 sacks cement over perforations from 2003 through 2033 ft. Plug was tagged at 1948'. (11-22-80) Peabody Vann shot casing off at 1002'. Dowell pumped 35 sacks cement at stub and tagged the cement at 964'. Mud gel pumped into open hole. (11-23-80) Dowell pumped 35 sacks cement from 230' to 330' and plug was tagged at 200'. Dowell then pumped 15 sacks cement at surface and job was completed. Location was cleaned up and pits filled. (All plugs were allowed to set four hours before tagging)

Dry hole marker installed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: Martin B. Muncy TITLE: operator DATE: 1-15-81

APPROVED BY: Dee Sturteford TITLE: OIL AND GAS SUPERVISOR DATE: JAN 4 1982

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
BUREAU OF CONSERVATION COMMISSION

FEB 24 1981

O. C. D.
ARTESIA, NEW MEXICO

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Free ☐
5. State Oil & Gas Lease No.
L-4039

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR RE-ENTER FOR SUCH PURPOSES.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Martin B. Muncy	8. Party or Lease Name WFM State
3. Address of Operator P.O. Box 196 Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER A, 330 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 36, TOWNSHIP 6S, RANGE 27E, NMPM.	10. Field and Pool, or Wildcat wildcat
11. Elevation (Show whether DF, RT, GR, etc.) 3940.8	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A permanent plug was set at 2240'. Dowell pumped 25 sacks cement over perforations from 2003 through 2033 ft. Plug was tagged at 1948'. (11-22-80) Peabody Vann shot casing off at 1002'. Dowell pumped 35 sacks cement at stub and tagged the cement at 964'. Mud gel pumped into open hole. (11-23-80) Dowell pumped 35 sacks cement from 230' to 330' and plug was tagged at 200'. Dowell then pumped 15 sacks cement at surface and job was completed. Location was cleaned up and pits filled. (All plugs were allowed to set four hours before tagging)

Dry hole marker installed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dustin B. Muncy TITLE operator DATE 04-15-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: