

N.M.O.C.D. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 20952

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Kenna Federal 30-

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat J. D. Wash

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T4S, R29E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry NOV 8 1982

2. NAME OF OPERATOR

Enserch Exploration, Inc. ✓

3. ADDRESS OF OPERATOR

O. C. D.
ARTESIA OFFICE

P. O. Box 4815, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

Unit H, 1980' FNL & 660' FEL, Sec. 30, T4S, R29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4403' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/21-24/80: Rigged up Permian Basin Casing Pullers. Set Baker CIBP at 6100' w/35' Class "H" Neat cement on top of plug. Cut off 5½" casing at 5418' and pulled out of hole. Laid 30 sack Class "H" Neat cement plug from 5468'-5368'. Laid 35 sack Class "H" Neat cement plug from 2059'-1959'. Laid 66' surface plug w/25 sacks Class "H" Neat cement. Cut off casinghead. Welded on dry hole marker. Preparing to clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Prod. Superintendent

DATE 6-10-80

(This space for Federal or State office use)

APPROVED BY

(Cec. Seal) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 5 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side