

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

MAY 12 1980

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.  
30-005-60675

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- ARTESIA, OFFICE	7. Unit Agreement Name
2. Name of Operator Enserch Exploration, Inc.	8. Farm or Lease Name J. G. O'Brien
3. Address of Operator 7701 North Stemmons Frwy. Suite 800 Dallas, Texas 75247	9. Well No. 1
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AT 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 7S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether LF, RT, GR, etc.) 4020 GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Drilling Operations <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 17-1/2" hole on 4-27-80. Drilled to 413' and set 13-3/8" casing. Cemented casing with 450 sks cement. Circulate cement to surface. Tested BOP's and casing. Drilled 12-1/4" hole to 2795'. Set 9-5/8" casing. Cemented with 1300 sks of cement. Circulate cement to surface. Nipple up additional BOP equipment and tested BOP's and casing. Presently drilling 8-3/4" hole at 3940'. (5-8-80)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. H. Peeples TITLE Regional Drilling Manager DATE May 9, 1980

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: