

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED

MAR 21 1980

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator John P. DiPaolo	8. Farm or Lease Name Cannon - Fee
3. Address of Operator P. O. Box 342, Roswell, New Mexico 88201	9. Well No. 1
4. Location of well UNIT LETTER H FEET FROM THE 2310 North LINE AND 330 FEET FROM THE East LINE, SECTION 17 TOWNSHIP 10-S RANGE 25-E NMPM.	10. Field and Pool, or Wildcat West Bitter Lakes
11. Elevation (Show whether DF, RT, GR, etc.) 3521.9 Gr.	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

I propose to drill an 11" hole to 670', run 7", 20#, API J-55 casing to total depth, and cement with a sufficient amount of cement to circulate to the surface. Then drill a 6 1/4" hole to 850', run 4 1/2", 9 1/2#, API J-55 production casing to total depth and cement with a sufficient amount of cement to circulate to the surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Grant E. Harrington TITLE Agent DATE March 20, 1980

APPROVED BY W. A. Gressett TITLE Chief of Division DATE March 20, 1980

CONDITIONS OF APPROVAL, IF ANY: