

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE	1	
ILE	1	
U.S.G.S.		
AND OFFICE		
OPERATOR	1	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- Dry Hole

Name of Operator
Yates Petroleum Corporation /

Address of Operator
207 S. 4th, Artesia, NM 88210

Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
East LINE, SECTION 8 TOWNSHIP 10S RANGE 26E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3800 GL, 3811 KB

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
L 4606

7. Unit Agreement Name

8. Farm or Lease Name
Sink Hole NR State Com.

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat No.

12. County
Chaves

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as follows:

Load hole with heavy mud.
Cut & pull 5½" casing from 3325'.
Set 100' plug 4080'-4180' across top perfs @4131-35'.
Set 100' plug across 5½" stub (50' in & out) approximately 3275'-3375' and tag.
Set 100' plug 2150'-2250' across Glorietta top.
Set plug 875'-1053' across surface casing shoe (926') and San Andres top (1003') & tag.
Set 15 sack surface plug and abandonment market.
Clean and level location.

Verbal approval for the above procedure obtained from Mike Williams on 7/29/80, subject to notifying NMOCD office prior to setting plugs.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Albert R. Hall TITLE Engineer DATE 7/29/80

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE JUL 31 1980

CONDITIONS OF APPROVAL, IF ANY: