



BRUCE KING  
GOVERNOR  
LARRY KEHOE  
SECRETARY

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
ARTESIA DISTRICT OFFICE

July 31, 1980

P.O. DRAWER DD  
ARTESIA, NEW MEXICO 88210  
(505) 746-4861

McClellan Oil Corp.  
P. O. Drawer 730  
Roswell, New Mexico 88201

Re: Jack L  
#1-M-14-6-27  
Chaves County, NM

Gentlemen:

We are returning the enclosed C-103 on the subject well for additions.

Please report the perfs, if any, in the 4½" casing.

Your attention to this matter will be appreciated.

Sincerely,

A handwritten signature in cursive script that reads "Mike Williams".

Mike Williams  
Oil & Gas Inspector

MW:ar

Encls.

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

JUL 31 1980

O. C. D.  
ARTESIA OFFICE

3a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Jack L
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Chaves

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Dry Hole
2. Name of Operator McClellan Oil Corporation ✓
3. Address of Operator Post Office Drawer 730, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER M, 860 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 6-S RANGE 27-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

4106 G. L. 4119 D. F

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐PLUG AND ABANDON ☒  
CHANGE PLANS ☐REMEDIAL WORK ☐  
COMMENCE DRILLING C-VS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P & A this test by spotting cement plug. 4700'-5130' (PBTD).  
100' plug over stub of 4½" casing at approximately 4200'. (Top cement 4270' by temperature survey.) 100' plug in and out of 8-5/8" casing at 1400'-1500'. 10 sx plug at surface.  
Heavy mud will be pumped between plugs. Set dry hole marker. Pits and location will be utilized for drilling the 1-X.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe J. McClellanTITLE OperatorDATE July 28, 1980

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: