

State of New Mexico
Energy, Minerals and Natural Resources Department

DISTRICT I

P.O. Box 1980, Hobbs NM 88240

DISTRICT II

P.O. Drawer DD, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO 30-005-60713

5. Indicate Type of Lease
State ☒ FEE ☐

6. State Oil & Gas Lease No.
V-1361

7. Lease Name or Unit Agreement Name
LATHAM STATE

8. Well No.
1

9. Pool Name or Wildcat
BROWN GRAYBURG QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL GAS
WELL ☒ WELL ☐ OTHER

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 South 4th., Artesia, NM 88210

4. Well Location
Unit Letter P 330 Feet From The SOUTH Line and 330 Feet From The EAST Line
Section 25 Township 10S Range 26E NMPM CHAVES COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3705' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM-REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-23-02 - MIRU PU; prep to P & A well
3-26-02 - Notified OCD 3-22-02, Mr. Hawkins, of operations. Loaded tubing & NU BOP. TOH w/ tubing & packer. Packer was not set. TIH w/ tubing; tagged PBTD @ 938'. Circ hole w/ 10# plugging mud. Pumped 30 sx "C" Neat cement + 2% CaCl2 from 930-550'. TOH & waited 3 hrs. TIH & tagged cement @ 500'; pulled up. Pumped cement from 400-200'. TOH & shut in. RU wireline, TIH w/ 3-3/8" casing gun, tag cement @ 120' - pull up. Perforate .4 holes @ 85', TOH. RD wireline, RU DS. Circ "C" Neat cement down 4-1/2", up 8-5/8" casing. RD DS. NU dry hole marker - well is P & A.

I hereby certify that the information above is a true and complete to the best of my knowledge and belief.

SIGNATURE *Donna Clack*

TITLE Operations Technician

DATE 2/27/02

TYPE OR PRINT NAME DONNA CLACK

Paul Sep

TELEPHONE NO 505-748-1471

(This space for State Use)

APPROVED BY

TITLE

DATE

APR 23 2002

CONDITIONS OF APPROVAL, IF ANY.