

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

MAY 20 1983

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator JFG ENTERPRISES ✓	8. Farm or Lease Name LUCKY TODD
3. Address of Operator P.O. BOX 100, ARTESIA, NEW MEXICO 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>WEST</u> LINE AND <u>660</u> FEET FROM <u>660</u> FEET FROM THE <u>SOUTH</u> LINE, SECTION <u>18</u> TOWNSHIP <u>7 S</u> RANGE <u>29 E</u> NMPM.	10. Field and Pool, or Wildcat BULL'S EYE-SAN ANDRES
15. Elevation (Show whether DF, RT, GR, etc.) GR 4032	12. County CHAVES

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SPOT 150' PLUG @ PERF. @2561-2578.
2. SPOT 150' PLUG @ BASE OF SALT 1500-1600.
3. SPOT 50' PLUG IN & OUT OF 4½" CASING @ APPROX. 1900'. * + Tag
4. SPOT 100' PLUG @ BASE OF 8-5/8" (426') 376-476. * + Tag
5. 10' PLUG @ SURFACE.
6. INSTALL DRY HOLE MARKER & DO CLEANUP.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. B. Fletcher

TITLE AGENT

DATE 5-20-1983

APPROVED BY M. A. Walker

TITLE OIL AND GAS INSPECTOR

DATE

MAY 23 1983