

N. O.C.D. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other)	<input type="checkbox"/>	<input type="checkbox"/>

5. LEASE NM-A-12125	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME APR 13 1981	
8. FARM OR LEASE NAME Coffman NY Federal	
9. WELL NO. 1	
10. FIELD OR WILDCAT NAME Wildcat	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit E, Sec. 25-T7S-R25E	
12. COUNTY OR PARISH Chaves	13. STATE NM
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 3650'	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

APR 13 1981

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set 1.81" standing valve in packer at 3993'. Killed well. WIH w/Steel Strip gun on wireline & perforated 3678-3892' w/13 .50" holes as follows: 3678, 79, 80, 81, 3780, 82, 3861, 63, 88, 89, 90, 91 & 92'. Straddled zone at 3888-3892' & 3861-3868' & broke perforations. Acidized perforations w/1000 gallons 7½% Spearhead acid & ball sealers. Ran bridge plug & packer & straddled zone 3678-3681' & 3780-3782'. Acidized w/1500 gallons 7½% Spearhead acid & 1000 SCF N2 per bbl. Pulled bridge plug, packer & tubing out of well. Ran 117 joints of 2-3/8" J-55 tubing open-ended to 3690'. Frac'd perforations 3678-3892' w/80000 gallons gelled 2% KCL water, 10000# CO2 & 90000# 20/40 sand. Well cleaned up and flowed 500# on 1/2" choke = 3000 mcf/d. Production prior to additional perforations approximately 230 mcf/d.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct.

SIGNED *Janita Lovell*

TITLE Secretary

DATE 4-9-81

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

APR 14 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side